

February 3, 2020

George Austin
Huntington UFSD
Oakwood and Mckay Roads
Huntington, NY 11743

RE: Lead Remediation Plan has been updated – April 14, 2020

I. Executive Summary

The Huntington Union Free School District has developed their 2020 Lead in Drinking Water Sampling and Analysis Program, as required by the New York State Department of Health (Public Health Law Sections 1370-a and 1110, Subpart 67-4 Lead Testing in School Drinking Water).

In accordance with the regulation, this Lead Remediation Plan is prepared to identify locations deemed as Applicable Drinking Water Sources and report first draw sample results, to mitigate locations where sample results exceed 15 parts per billion, to identify locations deemed as Non-Applicable Water Sources, communicate this designation to building occupants, and to develop strategies for monitoring locations deemed Non-Applicable Water Sources to insure building occupants do not consume water from these locations.

Within the Huntington Union Free School District, the following locations have been deemed Applicable Drinking Water Sources by the administration:

- 1) Water fountains and bottle filling stations;
- 2) Kitchen water faucets and pot fillers used in food preparation;
- 3) Ice machines
- 4) Elementary School classroom sinks
- 5) Elementary School bathroom sinks

First draw samples were collected from each of these locations within the District, and analyzed by a New York State Department of Health ELAP certified laboratory. For results at or below 15 ppb, no further action is required until 2025. For locations above 15 ppb, options include: second and third draw sample collection to determine source of lead, designation of the location as Non-applicable Water Source, or permanent removal of the fixture from the location. In either case, the result was communicated by Enviroscience Consultants, and the fixture was shut off by the District immediately upon receipt of results.

The following locations within the Huntington Union Free School District were deemed Non-Applicable Water Sources by the administration:

- 1) Science Laboratory sinks;
- 2) Art Room sinks;
- 3) Other classroom sinks;
- 4) Other Bathroom sinks;
- 5) Outside spigots
- 6) Custodial Closet sinks

In these cases, the District has placed signs adjacent to the fixture to notify occupants that the water is not intended for consumption. To further support this protocol, the following management of the locations is required:

- 1) Science Laboratory sinks - communicate in writing with students that these locations are for science experiments and hand washing only, not for consumption. This is most easily accomplished by including this language in the laboratory safety paperwork distributed to students at the beginning of the school year. This program should be monitored by the respective science teachers, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 2) Art Room sinks - communicate in writing to students that these locations are for cleaning of art supplies and hand washing only, not for consumption. This is most easily accomplished by including this language in the course paperwork distributed to students at the beginning of the school year. This program should be monitored by the respective art teachers, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 3) Other classroom sinks - classrooms in this category often include elementary classrooms, where students are to hand wash after bathroom usage or activities as part of a regular hygiene program. This program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 4) Bathroom sinks - in intermediate buildings, signage should be sufficient for communicating the concept of hand washing only. In elementary schools, personal hygiene should be integrated into curriculum to ensure students understand bathroom sinks are for hand washing only, and not consumption. Further, show what the signage looks like in bathrooms so they learn to recognize its meaning. This program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 5) Outside spigots - all-weather signage will be installed at each location. Further, spigots will have a special key maintained by the custodial staff to ensure that non-authorized persons do not fill sports coolers or use hoses for consumption. This program should be monitored by custodial staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 6) Custodial Closet sinks - these locations should be accessed by custodial personnel only, and locked when not in use. Access to others should be restricted. This program should be monitored by custodial staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

II. Sampling Procedures:

In accordance with the regulation, Enviroscience Consultants, Inc. performed initial water sampling throughout the Huntington School District from January 7-23, 2020. Samples were collected in wide-mouth 250 milliliter containers and were collected in the morning hours before the facilities opened. The water sources were not used for at least 8 hours and not more than 18 hours prior to sampling. Unique source numbers and designations were assigned to each source location. Unique sample identification numbers were assigned to each sample taken. The key to fixture type codes and the sampling location schematics are shown below.

Fixture Type Codes

BF	Bottle Filler
HB	Hose Bib
IM	Ice Machine
OS	Other Source
PF	Pot Filler
SK	Sink
SL	Supply Line
SP	Spigot
SPY	Spray
SS	Slop Sink
V	Valve
WC	Water Cooler
WF	Water Fountain

Source Designations

App	Applicable
N/A	Non-applicable

III. Initial Results:

All water source locations in each of the school buildings were assessed. Water source locations identified as drinking water sources were considered Applicable, and first draw samples were collected. Water source locations identified as non-drinking water sources were considered Non-applicable and these locations were documented.

The results of the initial sampling and the use of signs warning against water use at Non-applicable sources is documented in the School Water Outlet Inventory for each building (Appendix A through H).

All elevated locations should be taken off line until the remediation is completed. Any other drinking water sources in these buildings that were not functional at the time of initial sampling and have not been tested should be tested. All locations deemed non-applicable, but do not have signs, should be taken off line until signs have been posted.

The following is a summary of results in parts per billion (ppb) of locations where sample results were found above 15 ppb, the remedial action taken and final results where applicable:

Flower Hill Primary School

Kitchen Potfiller	PF	600	Permanently removed from service	-
Room 4	SK	18.3	Fixture Replacement	4.31
Room 4	WF	18.1	Fixture Replacement	2.17
Room 6 Bathroom	SK	227	Fixture Replacement	1.55
Room 11	WF	29.6	Fixture Replacement	5.12

Jefferson Primary School

Kitchen Bathroom	SK	370	Fixture Replacement	9.51
Hallway by Room 9	WF	31.5	Fixture Replacement	14.4
Room 4	SK	19	Fixture Replacement	5.26
Library Office	SK	17.9	Fixture Replacement	2.37

Room 21	WF	30.8	Fixture Replacement	4.48
Room 23	WF	15.8	Fixture Replacement	7.07
Boy's Bathroom by Room 24 @ A	SK	17	Fixture Replacement	10.8
Women's Bathroom by Room 24	SK	37.3	Fixture Replacement	9.69
Girl's Bathroom by Room 25 @ A	SK	99.7	Fixture Replacement	5.16
Physical Education Office	SK	161	Fixture Replacement	3.77

Southdown Primary School

Faculty Lounge	WF	25.1	Permanently removed from service
Room 2	WF	44.1	Permanently removed from service

Washington Primary School

No Exceedances

Jack Abrams STEM Magnet School

Girls Bathroom by Room 210 @ C	SK	15.2	Fixture Replacement	12.8
Room 203	SK	312	Fixture Replacement	7.71
Room 201	SK	15.8	Fixture Replacement	3.72
Room 202	SK	22.3	Fixture Replacement	8.84
STEM Director K-12	SK	26.6	Fixture Replacement	7.69
Room 210	SK	270	Fixture Replacement	14
Room 210	WF	33	Fixture Replacement	6.18
Girls Bathroom by Room 213 @ B	SK	31.9	Fixture Replacement	<1.0
Administration Breakroom	WF	86.8	Permanently removed from service	-
Assistant Superintendent	SK	91	Fixture Replacement	2.42
Girls Locker Room	WF	77.2	Permanently removed from service	-
Girls Locker Room @ A	SK	21.6	Fixture Replacement	3.84
Boys Locker Room	SK	81.8	Fixture Replacement	11.4

Boys Locker Room	WF	30.4	Fixture Replacement	4.26
Room 117 Bathroom	SK	15.9	Fixture Replacement	3.67
Room 114	WF	17.7	Fixture Replacement	3.08

Woodhull Intermediate School

Room 10	WF	20.3	Permanently removed from service
---------	----	------	----------------------------------

J. Taylor Finley Middle School

Dishwashing Station	SK	30	Fixture Replacement	3.34
Prep Room 110 / 109 Counter 1 @ B	SK	35	Permanent Sign Posted	-
Room 208 Station 1	SK	66.6	Fixture Replacement	4.84
Room 208 Station 2	SK	107	Fixture Replacement	3.81
Room 207 Station 3	SK	17	Fixture Replacement	5.22

Huntington High School

Kitchen Prep @A	SK	22.4	Fixture Replacement	<1.0
Kitchen Prep @B	SK	27.3	Fixture Replacement	<1.0
Kitchen Pot Filler by Stove	PF	62.8	Permanently removed from service	-
Kitchen Pot Filler Spray by Oven	SPY	20.7	Permanently removed from service	-
Room 161	SK	15.1	Fixture Replacement	4.48
Library Office (Room 110)	SK	178	Fixture Replacement	1.39
Trainer's Vestibule	WF	16.8	Fixture Replacement	2.92

Districtwide Lead in Drinking Water Sampling and Remediation Plan

Table of Contents

- I. Executive Summary
- II. Sampling Methodology
- III. Initial Results

Appendix A – Flower Hill Primary School

Appendix B – Jefferson Primary School

Appendix C – Southdown Primary School

Appendix D – Washington Primary School

Appendix E – Jack Abrams STEM Magnet School

Appendix F – Woodhull Intermediate School

Appendix G – J. Taylor Finley Middle School

Appendix H – Huntington High School

Appendix A

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1000-1	Kitchen Dishwash @ A	SK	App	3.2	1/8/2020	-	-	-	None	-	-	-
1000-2	Kitchen Dishwash @ B	SK	App	2.36	1/8/2020	-	-	-	None	-	-	-
1000-3	Kitchen Dishwash @ C	SPY	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1000-4	Kitchen Handwash	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1000-5	Kitchen Potfiller	PF	App	600	1/8/2020				None	CAPPED		
1001-1	Room 15 Bathroom	SK	App	14.5	1/8/2020	-	-	-	None	-	-	-
1002-1	Girl's Bathroom by Room 16 @ A	SK	App	2.04	1/8/2020	-	-	-	None	-	-	-
1002-2	Girl's Bathroom by Room 16 @ B	SK	App	1.87	1/8/2020	-	-	-	None	-	-	-
1002-3	Girl's Bathroom by Room 16 @ C	SK	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1003-1	Custodial Closet by Room 16	SS	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1004-1	Room 16	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1004-2	Room 16	WF	App	1.61	1/8/2020	-	-	-	None	-	-	-
1005-1	Boy's Bathroom by Room 16 @ A	SK	App	3.02	1/8/2020	-	-	-	None	-	-	-
1005-2	Boy's Bathroom by Room 16 @ B	SK	App	1.86	1/8/2020	-	-	-	None	-	-	-
1005-3	Boy's Bathroom by Room 16 @ C	SK	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1006-1	Room 17	SK	App	1.18	1/8/2020	-	-	-	None	-	-	-
1006-2	Room 17	WF	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1007-1	Hallway by Room 17	WF	App	1.93	1/8/2020	-	-	-	None	-	-	-
1008-1	Room 18	SK	App	1.21	1/8/2020	-	-	-	None	-	-	-
1009-1	Room 20	SK	App	2.28	1/8/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1009-2	Room 20	WF	App	5.85	1/8/2020	-	-	-	None	-	-	-
1010-1	Room 21	SK	App	2.28	1/8/2020	-	-	-	None	-	-	-
1010-2	Room 21	WF	App	3.79	1/8/2020	-	-	-	None	-	-	-
1011-1	Room 22	SK	App	2.38	1/8/2020	-	-	-	None	-	-	-
1011-2	Room 22	WF	App	2.24	1/8/2020	-	-	-	None	-	-	-
1012-1	Hallway by Gym	BF	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1012-2	Hallway by Gym	WF	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1013-1	Custodial Closet by Kitchen	SS	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1014-1	Adult Bathroom by Gym	SK	App	1.43	1/8/2020	-	-	-	None	-	-	-
1015-1	Nurse's Bathroom	SK	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1016-1	Faculty Lounge	SK	App	1.23	1/8/2020	-	-	-	None	-	-	-
1017-1	Women's Bathroom by Faculty Lounge @ A	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1017-2	Women's Bathroom by Faculty Lounge @ B	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1018-1	Hallway by Room 8	WF	App	1.66	1/8/2020	-	-	-	None	-	-	-
1019-1	Room 7	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1019-2	Room 7	WF	App	1.4	1/8/2020	-	-	-	None	-	-	-
1019-3	Room 7 Bathroom	SK	App	1.4	1/8/2020	-	-	-	None	-	-	-
1020-1	Room 5	SK	App	2.04	1/8/2020	-	-	-	None	-	-	-
1020-2	Room 5	WF	App	2.42	1/8/2020	-	-	-	None	-	-	-
1020-3	Room 5 Bathroom	SK	App	1.28	1/8/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1021-1	Room 3	SK	App	1.28	1/8/2020	-	-	-	None	-	-	-
1021-2	Room 3	WF	App	5.81	1/8/2020	-	-	-	None	-	-	-
1021-3	Room 3 Bathroom	SK	App	7.68	1/8/2020	-	-	-	None	-	-	-
1022-1	Room 1	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1022-2	Room 1	WF	App	9	1/8/2020	-	-	-	None	-	-	-
1022-3	Room 1 Bathroom	SK	App	3.43	1/8/2020	-	-	-	None	-	-	-
1023-1	Room 2	SK	App	1.52	1/8/2020	-	-	-	None	-	-	-
1023-2	Room 2	WF	App	1.01	1/8/2020	-	-	-	None	-	-	-
1023-3	Room 2 Bathroom	SK	App	3.88	1/8/2020	-	-	-	None	-	-	-
1024-1	Room 4	SK	App	4.31	2/12/2020	-	-	-	None	-	-	-
1024-2	Room 4	WF	App	2.17	2/12/2020	-	-	-	None	-	-	-
1024-3	Room 4 Bathroom	SK	App	2.79	1/8/2020	-	-	-	None	-	-	-
1025-1	Room 6	SK	App	6.56	1/8/2020	-	-	-	None	-	-	-
1025-2	Room 6	WF	App	2.39	1/8/2020	-	-	-	None	-	-	-
1025-3	Room 6 Bathroom	SK	App	1.55	2/12/2020	-	-	-	None	-	-	-
1026-1	Room 8	SK	App	3.88	1/8/2020	-	-	-	None	-	-	-
1026-2	Room 8	WF	App	2.39	1/8/2020	-	-	-	None	-	-	-
1026-3	Room 8 Bathroom	SK	App	7.95	1/8/2020	-	-	-	None	-	-	-
1027-1	Girl's Bathroom by Room 8 @ A	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1027-2	Girl's Bathroom by Room 8 @ B	SK	App	1.08	1/8/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1028-1	Custodial Closet by Room 8	SS	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1029-1	Boy's Bathroom by Room 8 @ A	SK	App	1.66	1/8/2020	-	-	-	None	-	-	-
1029-2	Boy's Bathroom by Room 8 @ B	SK	App	2.78	1/8/2020	-	-	-	None	-	-	-
1030-1	Room 10	SK	App	1.79	1/8/2020	-	-	-	None	-	-	-
1030-2	Room 10	WF	App	1.74	1/8/2020	-	-	-	None	-	-	-
1031-1	Room 12	SK	App	1.97	1/8/2020	-	-	-	None	-	-	-
1031-2	Room 12	WF	App	1.89	1/8/2020	-	-	-	None	-	-	-
1032-1	Room 14	SK	App	1.91	1/8/2020	-	-	-	None	-	-	-
1032-2	Room 14	WF	App	1.87	1/8/2020	-	-	-	None	-	-	-
1033-1	Room 13	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1033-2	Room 13	WF	App	2.91	1/8/2020	-	-	-	None	-	-	-
1034-1	Room 11	SK	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1034-2	Room 11	WF	App	5.12	2/12/2020	-	-	-	None	-	-	-
1035-1	Custodial Office Bathroom	SK	App	4.34	1/8/2020	-	-	-	None	-	-	-

Laboratory Report

NYE Report #: 2200088-13600

January 9, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Flower Hill Primary, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on January 08, 2020. New York Environmental analyzed the samples on January 09, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	08 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P001	1	Kitchen Dishwash @ A - SK; Initial	1.00	3.20	µg/L	
200108P002	2	Kitchen Dishwash @ B - SK; Initial	1.00	2.36	µg/L	
200108P003	3	Kitchen Dishwash @ C - SPY; Initial	1.00	<1.00	µg/L	
200108P004	4	Kitchen Dishwash @ D - SK; Initial	1.00	<1.00	µg/L	
200108P005	5	Kitchen Potfiller - PF; Initial	1.00	600	µg/L	E,H
200108P006	6	Room 15-BR - SK; Initial	1.00	14.5	µg/L	
200108P007	7	Girl's Bathroom by Room 16 @ A - SK; Initial	1.00	2.04	µg/L	
200108P008	8	Girl's Bathroom by Room 16 @ B - SK; Initial	1.00	1.87	µg/L	
200108P009	9	Room 16 - SK; Initial	1.00	<1.00	µg/L	
200108P010	10	Room 16 - WF; Initial	1.00	1.61	µg/L	
200108P011	11	Boy's Bathroom by Room 16 @ A - SK; Initial	1.00	3.02	µg/L	
200108P012	12	Boy's Bathroom by Room 16 @ B - SK; Initial	1.00	1.86	µg/L	
200108P013	13	Room 17 - SK; Initial	1.00	1.18	µg/L	
200108P014	14	Room 17 - WF; Initial	1.00	<1.00	µg/L	
200108P015	15	Hallway by Room 17 - WF; Initial	1.00	1.93	µg/L	
200108P016	16	Room 18 - 0; Initial	1.00	1.21	µg/L	
200108P017	17	Room 20 - SK; Initial	1.00	2.28	µg/L	
200108P018	18	Room 20 - WF; Initial	1.00	5.85	µg/L	
200108P019	19	Room 21 - SK; Initial	1.00	2.28	µg/L	
200108P020	20	Room 21 - WF; Initial	1.00	3.79	µg/L	
200108P021	21	Room 22 - SK; Initial	1.00	2.38	µg/L	
200108P022	22	Room 22 - WF; Initial	1.00	2.24	µg/L	
200108P023	23	Hallway by Gym - BF; Initial	1.00	<1.00	µg/L	
200108P024	24	Hallway by Gym - WF; Initial	1.00	<1.00	µg/L	
200108P025	25	Adult Bathroom by Gym - SK; Initial	1.00	1.43	µg/L	
200108P026	26	Faculty Lounge - SK; Initial	1.00	1.23	µg/L	



Date Collected:	08 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P027	27	Women's Bathroom by Faculty Lounge @ A - SK; Initial	1.00	<1.00	µg/L	
200108P028	28	Women's Bathroom by Faculty Lounge @ B - SK; Initial	1.00	<1.00	µg/L	
200108P029	29	Hallway by Room 8 - WF; Initial	1.00	1.66	µg/L	
200108P030	30	Room 7 - SK; Initial	1.00	<1.00	µg/L	
200108P031	31	Room 7 - WF; Initial	1.00	1.40	µg/L	
200108P032	32	Room 7 Bathroom - SK; Initial	1.00	1.40	µg/L	
200108P033	33	Room 5 - SK; Initial	1.00	2.04	µg/L	
200108P034	34	Room 5 - WF; Initial	1.00	2.42	µg/L	
200108P035	35	Room 5 Bathroom - SK; Initial	1.00	1.28	µg/L	
200108P036	36	Room 3 - SK; Initial	1.00	1.28	µg/L	
200108P037	37	Room 3 - WF; Initial	1.00	5.81	µg/L	
200108P038	38	Room 3 Bathroom - SK; Initial	1.00	7.68	µg/L	
200108P039	39	Room 1 - SK; Initial	1.00	<1.00	µg/L	
200108P040	40	Room 1 - WF; Initial	1.00	9.00	µg/L	
200108P041	41	Room 1 Bathroom - SK; Initial	1.00	3.43	µg/L	
200108P042	42	Room 2 - SK; Initial	1.00	1.52	µg/L	
200108P043	43	Room 2 - WF; Initial	1.00	1.01	µg/L	
200108P044	44	Room 2 Bathroom - SK; Initial	1.00	3.88	µg/L	
200108P045	45	Room 4 - SK; Initial	1.00	18.3	µg/L	H
200108P046	46	Room 4 - WF; Initial	1.00	18.1	µg/L	H
200108P047	47	Room 4 Bathroom - SK; Initial	1.00	2.79	µg/L	
200108P048	48	Room 6 - SK; Initial	1.00	6.56	µg/L	
200108P049	49	Room 6 - WF; Initial	1.00	2.39	µg/L	
200108P050	50	Room 6 Bathroom - SK; Initial	1.00	227	µg/L	E,H
200108P051	51	Room 8 - SK; Initial	1.00	3.88	µg/L	
200108P052	52	Room 8 - WF; Initial	1.00	2.39	µg/L	
200108P053	53	Room 8 Bathroom - SK; Initial	1.00	7.95	µg/L	



Date Collected:	08 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P054	54	Girl's Bathroom by Room 8 @ A - SK; Initial	1.00	<1.00	µg/L	
200108P055	55	Girl's Bathroom by Room 8 @ B - SK; Initial	1.00	1.08	µg/L	
200108P056	56	Boy's Bathroom by Room 8 @ A - SK; Initial	1.00	1.66	µg/L	
200108P057	57	Boy's Bathroom by Room 8 @ B - SK; Initial	1.00	2.78	µg/L	
200108P058	58	Room 10 - SK; Initial	1.00	1.79	µg/L	
200108P059	59	Room 10 - WF; Initial	1.00	1.74	µg/L	
200108P060	60	Room 12 - SK; Initial	1.00	1.97	µg/L	
200108P061	61	Room 12 - WF; Initial	1.00	1.89	µg/L	
200108P062	62	Room 14 - SK; Initial	1.00	1.91	µg/L	
200108P063	63	Room 14 - WF; Initial	1.00	1.87	µg/L	
200108P064	64	Room 13 - SK; Initial	1.00	<1.00	µg/L	
200108P065	65	Room 13 - WF; Initial	1.00	2.91	µg/L	
200108P066	66	Room 11 - SK; Initial	1.00	<1.00	µg/L	
200108P067	67	Room 11 - WF; Initial	1.00	29.6	µg/L	H
200108P068	68	Custodial Office Bathroom - SK; Initial	1.00	4.34	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2200708-13950

February 14, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Flower Hill Primary School, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 14, 2020. New York Environmental analyzed the samples on February 14, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	12 Feb 2020
Date Received:	14 Feb 2020
Date Analyzed:	14 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
200214K002	1	Room 11 - WF; Initial	1.00	5.12	µg/L	
200214K003	2	Room 6 Bathroom - SK; Initial	1.00	1.55	µg/L	
200214K004	3	Room 4 - SK; Initial	1.00	4.31	µg/L	
200214K005	4	Room 4 - WF; Initial	1.00	2.17	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix B

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1000-1	Kitchen Island	SK	App	2.92	1/9/2020	-	-	-	None	-	-	-
1000-2	Kitchen handwash	SK	App	9.42	1/9/2020	-	-	-	None	-	-	-
1000-3	Kitchen Dishwash	SK	App	2.34	1/9/2020	-	-	-	None	-	-	-
1000-4	Kitchen Dishwash	SPY	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1000-5	Kitchen Bathroom	SK	App	9.51	2/12/2020	-	-	-	None	-	-	-
1001-1	Gym Vestibule	BF	App	7.55	1/9/2020	-	-	-	None	-	-	-
1001-2	Gym Vestibule	WF	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1002-1	Hallway by Cafeteria	WF	App	2.04	1/9/2020	-	-	-	None	-	-	-
1003-1	Adult Bathroom	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1004-1	Nurse's Office	SK	App	3.34	1/9/2020	-	-	-	None	-	-	-
1004-2	Nurse's Office Bathroom	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1005-1	Hallway by Room 9	WF	App	14.4	2/27/2020	-	-	-	None	-	-	-
1006-1	Room 9	SK	App	4.53	1/9/2020	-	-	-	None	-	-	-
1007-1	Room 7	SK	App	9.06	1/9/2020	-	-	-	None	-	-	-
1007-2	Room 7	WF	App	3.6	1/9/2020	-	-	-	None	-	-	-
1008-1	Room 5	SK	App	4.99	1/9/2020	-	-	-	None	-	-	-
1008-2	Room 5	WF	App	6.26	1/9/2020	-	-	-	None	-	-	-
1009-1	Room 3	SK	App	2.24	1/9/2020	-	-	-	None	-	-	-
1009-2	Room 3	WF	App	4.92	1/9/2020	-	-	-	None	-	-	-
1010-1	Room 1	SK	App	8.24	1/9/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1010-2	Room 1	WF	App	3.49	1/9/2020	-	-	-	None	-	-	-
1011-1	Room 2	SK	App	3.01	1/9/2020	-	-	-	None	-	-	-
1011-2	Room 2	WF	App	3.75	1/9/2020	-	-	-	None	-	-	-
1012-1	Room 4	SK	App	5.26	2/12/2020	-	-	-	None	-	-	-
1012-2	Room 4	WF	App	2.62	1/9/2020	-	-	-	None	-	-	-
1013-1	Room 6	SK	App	2.9	1/9/2020	-	-	-	None	-	-	-
1013-2	Room 6	WF	App	3.42	1/9/2020	-	-	-	None	-	-	-
1014-1	Room 8	SK	App	4.44	1/9/2020	-	-	-	None	-	-	-
1014-2	Room 8	WF	App	1.8	1/9/2020	-	-	-	None	-	-	-
1015-1	Men's Bathroom by Room 8	SK	App	4.32	1/9/2020	-	-	-	None	-	-	-
1016-1	Custodial Closet by Room 8	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1017-1	Women's Bathroom by Room 9	SK	App	6.03	1/9/2020	-	-	-	None	-	-	-
1018-1	Room 11 Faculty Room	SK	App	5.25	1/9/2020	-	-	-	None	-	-	-
1019-1	Room 12 Bathroom	SK	App	5.84	1/9/2020	-	-	-	None	-	-	-
1020-1	Room 14	SK	App	4.51	1/9/2020	-	-	-	None	-	-	-
1020-2	Room 14	WF	App	4.59	1/9/2020	-	-	-	None	-	-	-
1020-3	Room 14 Bathroom	SK	App	4.63	1/9/2020	-	-	-	None	-	-	-
1021-1	Library Office	SK	App	2.36	2/27/2020	-	-	-	None	-	-	-
1021-2	Library	SK	App	8.97	1/9/2020	-	-	-	None	-	-	-
1022-1	Room 17	SK	App	11	1/9/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1022-2	Room 17	WF	App	13.2	1/9/2020	-	-	-	None	-	-	-
1023-1	Room 19	SK	App	12	1/9/2020	-	-	-	None	-	-	-
1023-2	Room 19	WF	App	3.08	1/9/2020	-	-	-	None	-	-	-
1024-1	Room 18	SK	App	6.61	1/9/2020	-	-	-	None	-	-	-
1024-2	Room 18	WF	App	3.48	1/9/2020	-	-	-	None	-	-	-
1025-1	Room 21	SK	App	11.2	1/9/2020	-	-	-	None	-	-	-
1025-2	Room 21	WF	App	4.48	2/12/2020	-	-	-	None	-	-	-
1026-1	Room 20	SK	App	2.83	1/9/2020	-	-	-	None	-	-	-
1026-2	Room 20	WF	App	5.39	1/9/2020	-	-	-	None	-	-	-
1027-1	Room 23	SK	App	6.7	1/9/2020	-	-	-	None	-	-	-
1027-2	Room 23	WF	App	7.07	2/23/2020	-	-	-	None	-	-	-
1028-1	Room 22	SK	App	4.92	1/9/2020	-	-	-	None	-	-	-
1028-2	Room 22	WF	App	4.63	1/9/2020	-	-	-	None	-	-	-
1029-1	Room 24	SK	App	1.43	1/9/2020	-	-	-	None	-	-	-
1029-2	Room 24	WF	App	2.83	1/9/2020	-	-	-	None	-	-	-
1030-1	Boy's Bathroom by Room 24 @ A	SK	App	10.8	2/12/2020	-	-	-	None	-	-	-
1030-2	Boy's Bathroom by Room 24 @ B	SK	App	12.1	1/9/2020	-	-	-	None	-	-	-
1030-3	Boy's Bathroom by Room 24 @ C	SK	App	7.7	1/9/2020	-	-	-	None	-	-	-
1030-4	Boy's Bathroom by Room 24 @ D	SK	App	14.3	1/9/2020	-	-	-	None	-	-	-
1030-5	Boy's Bathroom by Room 24 @ E	SK	App	11.2	1/9/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 st Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1031-1	Women's Bathroom by Room 24	SK	App	9.69	2/27/2020	-	-	-	None	-	-	-
1032-1	Girl's Bathroom by Room 25 @ A	SK	App	5.16	2/12/2020	-	-	-	None	-	-	-
1032-2	Girl's Bathroom by Room 25 @ B	SK	App	10.2	1/9/2020	-	-	-	None	-	-	-
1032-3	Room 25	SK	App	6.93	1/9/2020	-	-	-	None	-	-	-
1033-1	Room 25	SK	App	4	1/9/2020	-	-	-	None	-	-	-
1033-2	Room 26	SK	App	2.31	1/9/2020	-	-	-	None	-	-	-
1034-1	Room 26	SK	App	1.45	1/9/2020	-	-	-	None	-	-	-
1034-2	Room 27	SK	App	1.65	1/9/2020	-	-	-	None	-	-	-
1035-1	Room 27 Art Room	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1035-2	Room 27 Art Room	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1035-3	Room 27 Art Room	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1035-4	Room 27 Art Room	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1036-1	Custodial Closet by Kitchen	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1037-1	Physical Education Office	SK	App	3.77	2/27/2020	-	-	-	None	-	-	-
1038-1	Custodial Office Bathroom	SK	App	6.13	1/9/2020	-	-	-	None	-	-	-
1039-1	Custodial Closet by Room 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-

Laboratory Report

NYE Report #: 2200142-13607

January 13, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Jefferson Primary; Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on January 09, 2020. New York Environmental analyzed the samples on January 10, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	09 Jan 2020
Date Received:	09 Jan 2020
Date Analyzed:	10 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200109O001	1	Kitchen Island - SK; Initial	1.00	2.92	µg/L	
200109O002	2	Kitchen handwash - SK; Initial	1.00	9.42	µg/L	
200109O003	3	Kitchen Dishwash - SK; Initial	1.00	2.34	µg/L	
200109O004	4	Kitchen Bathroom - SK; Initial	1.00	370	µg/L	E,H
200109O005	5	Gym Vestibule - BF; Initial	1.00	7.55	µg/L	
200109O006	6	Gym Vestibule - WF; Initial	1.00	<1.00	µg/L	
200109O007	7	Hallway by Cafeteria - WF; Initial	1.00	2.04	µg/L	
200109O008	8	Nurse's Office - SK; Initial	1.00	3.34	µg/L	
200109O009	9	Hallway by Room 9 - WF; Initial	1.00	31.5	µg/L	H
200109O010	10	Room 9 - SK; Initial	1.00	4.53	µg/L	
200109O011	11	Room 7 - SK; Initial	1.00	9.06	µg/L	
200109O012	12	Room 7 - WF; Initial	1.00	3.60	µg/L	
200109O013	13	Room 5 - SK; Initial	1.00	4.99	µg/L	
200109O014	14	Room 5 - WF; Initial	1.00	6.26	µg/L	
200109O015	15	Room 3 - SK; Initial	1.00	2.24	µg/L	
200109O016	16	Room 3 - WF; Initial	1.00	4.92	µg/L	
200109O017	17	Room 1 - SK; Initial	1.00	8.24	µg/L	
200109O018	18	Room 1 - WF; Initial	1.00	3.49	µg/L	
200109O019	19	Room 2 - SK; Initial	1.00	3.01	µg/L	
200109O020	20	Room 2 - WF; Initial	1.00	3.75	µg/L	
200109O021	21	Room 4 - SK; Initial	1.00	19.0	µg/L	H
200109O022	22	Room 4 - WF; Initial	1.00	2.62	µg/L	
200109O023	23	Room 6 - SK; Initial	1.00	2.90	µg/L	
200109O024	24	Room 6 - WF; Initial	1.00	3.42	µg/L	
200109O025	25	Room 8 - SK; Initial	1.00	4.44	µg/L	
200109O026	26	Room 8 - WF; Initial	1.00	1.80	µg/L	



Date Collected:	09 Jan 2020
Date Received:	09 Jan 2020
Date Analyzed:	10 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200109O027	27	Men's Bathroom by Room 8 - SK; Initial	1.00	4.32	µg/L	
200109O028	28	Women's Bathroom by Room 9 - SK; Initial	1.00	6.03	µg/L	
200109O029	29	Room 11 Faculty Room - SK; Initial	1.00	5.25	µg/L	
200109O030	30	Room 12 Bathroom - SK; Initial	1.00	5.84	µg/L	
200109O031	31	Room 14 - SK; Initial	1.00	4.51	µg/L	
200109O032	32	Room 14 - WF; Initial	1.00	4.59	µg/L	
200109O033	33	Room 14 Bathroom - SK; Initial	1.00	4.63	µg/L	
200109O034	34	Library Office - SK; Initial	1.00	17.9	µg/L	H
200109O035	35	Library - SK; Initial	1.00	8.97	µg/L	
200109O036	36	Room 17 - SK; Initial	1.00	11.0	µg/L	
200109O037	37	Room 17 - WF; Initial	1.00	13.2	µg/L	
200109O038	38	Room 19 - SK; Initial	1.00	12.0	µg/L	
200109O039	39	Room 19 - WF; Initial	1.00	3.08	µg/L	
200109O040	40	Room 18 - SK; Initial	1.00	6.61	µg/L	
200109O041	41	Room 18 - WF; Initial	1.00	3.48	µg/L	
200109O042	42	Room 21 - SK; Initial	1.00	11.2	µg/L	
200109O043	43	Room 21 - WF; Initial	1.00	30.8	µg/L	H
200109O044	44	Room 20 - SK; Initial	1.00	2.83	µg/L	
200109O045	45	Room 20 - WF; Initial	1.00	5.39	µg/L	
200109O046	46	Room 23 - SK; Initial	1.00	6.70	µg/L	
200109O047	47	Room 23 - WF; Initial	1.00	15.8	µg/L	H
200109O048	48	Room 22 - SK; Initial	1.00	4.92	µg/L	
200109O049	49	Room 22 - WF; Initial	1.00	4.63	µg/L	
200109O050	50	Room 24 - SK; Initial	1.00	1.43	µg/L	
200109O051	51	Room 24 - WF; Initial	1.00	2.83	µg/L	
200109O052	52	Boy's Bathroom by Room 24 @ A - SK; Initial	1.00	17.0	µg/L	H
200109O053	53	Boy's Bathroom by Room 24 @ B - SK; Initial	1.00	12.1	µg/L	



Date Collected:	09 Jan 2020
Date Received:	09 Jan 2020
Date Analyzed:	10 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200109O054	54	Boy's Bathroom by Room 24 @ C - SK; Initial	1.00	7.70	µg/L	
200109O055	55	Boy's Bathroom by Room 24 @ D - SK; Initial	1.00	14.3	µg/L	
200109O056	56	Boy's Bathroom by Room 24 @ E - SK; Initial	1.00	11.2	µg/L	
200109O057	57	Women's Bathroom by Room 24 - SK; Initial	1.00	37.3	µg/L	H
200109O058	58	Girl's Bathroom by Room 25 @ A - SK; Initial	1.00	99.7	µg/L	E,H
200109O059	59	Girl's Bathroom by Room 25 @ B - SK; Initial	1.00	10.2	µg/L	
200109O060	60	Room 25 - SK; Initial	1.00	6.93	µg/L	
200109O061	61	Room 25 - SK; Initial	1.00	4.00	µg/L	
200109O062	62	Room 26 - SK; Initial	1.00	2.31	µg/L	
200109O063	63	Room 26 - SK; Initial	1.00	1.45	µg/L	
200109O064	64	Room 27 - SK; Initial	1.00	1.65	µg/L	
200109O065	65	Physical Education Office - SK; Initial	1.00	161	µg/L	E,H
200109O066	66	Custodial Office Bathroom - SK; Initial	1.00	6.13	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2200711-13953

February 14, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Jefferson Primary School, Huntington, NY

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 14, 2020. New York Environmental analyzed the samples on February 14, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	12 Feb 2020
Date Received:	14 Feb 2020
Date Analyzed:	14 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200214K012	1	Kitchen Bathroom - SK; Initial	1.00	9.51	µg/L	
200214K013	2	Hallway by Room 9 - WF; Initial	1.00	20.3	µg/L	H
200214K014	3	Room 4 - SK; Initial	1.00	5.26	µg/L	
200214K015	4	Library Office - SK; Initial	1.00	17.6	µg/L	H
200214K016	5	Room 21 - WF; Initial	1.00	4.48	µg/L	
200214K017	6	Room 23 - WF; Initial	1.00	7.07	µg/L	
200214K018	7	Boy's Bathroom by Room 24 @A - SK; Initial	1.00	10.8	µg/L	
200214K019	8	Women's Bathroom by Room 24 - SK; Initial	1.00	15.4	µg/L	H
200214K020	9	Girl's Bathroom by Room 25 @A - SK; Initial	1.00	5.16	µg/L	
200214K021	10	Physical Education Office - SK; Initial	1.00	23.4	µg/L	H

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2200948-14085

March 2, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Jefferson School Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 27, 2020. New York Environmental analyzed the samples on February 28, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	27 Feb 2020
Date Received:	27 Feb 2020
Date Analyzed:	28 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
200227O002	1	Hallway by Room 9-WF; Initial	1.00	14.4	µg/L	
200227O003	2	Library Office-SK; Initial	1.00	2.36	µg/L	
200227O004	3	Women's Bathroom by Room 24-SK; Initial	1.00	9.69	µg/L	
200227O005	4	Physical Education Office-SK; Initial	1.00	3.77	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation



Appendix C

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen Handwash	SK	App	4.09	1/8/2020	-	-	-	None	-	-	-
1001-2	Kitchen Dishwash Station @ A	SK	App	3.74	1/8/2020	-	-	-	None	-	-	-
1001-3	Kitchen Dishwash Station @ B	SK	App	3.5	1/8/2020	-	-	-	None	-	-	-
1001-4	Kitchen Dishwasher Spray	SPY	App	5.41	1/8/2020	-	-	-	None	-	-	-
1001-5	Kitchen Dishwasher Station Prep	SK	App	4.66	1/8/2020	-	-	-	None	-	-	-
1002-1	Room 15 Bathroom	SK	App	2.24	1/8/2020	-	-	-	None	-	-	-
1003-1	Room 16	SK	App	3.78	1/8/2020	-	-	-	None	-	-	-
1003-2	Room 16	WF	App	5.59	1/8/2020	-	-	-	None	-	-	-
1004-1	Room 17	SK	App	9.9	1/8/2020	-	-	-	None	-	-	-
1004-2	Room 17	WF	App		1/8/2020	-	-	-		CAPPED	-	-
1005-1	Room 18	SK	App	4.43	1/8/2020	-	-	-	None	-	-	-
1005-2	Room 18	WF	App	2.11	1/8/2020	-	-	-	None	-	-	-
1006-1	Room 19	SK	App	9.78	1/8/2020	-	-	-	None	-	-	-
1006-2	Room 19	WF	App	8.78	1/8/2020	-	-	-	None	-	-	-
1007-1	Room 21	SK	App	4.56	1/8/2020	-	-	-	None	-	-	-
1007-2	Room 21	WF	App	4.34	1/8/2020	-	-	-	None	-	-	-
1008-1	Room 22	SK	App	3.19	1/8/2020	-	-	-	None	-	-	-
1008-2	Room 22	WF	App	6.03	1/8/2020	-	-	-	None	-	-	-
1009-1	Hallway By Room 17	WF	App		1/8/2020	-	-	-	None	CAPPED	-	-
1010-1	Boys Bathroom by Room 16 @ A	SK	App	3.38	1/8/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1010-2	Boys Bathroom by Room 16 @ B	SK	App	4.07	1/8/2020	-	-	-	None	-	-	-
1010-3	Boys Bathroom by Room 16 @ C	SK	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1011-1	Girls Bathroom by Room 16 @ A	SK	App	8.02	1/8/2020	-	-	-	None	-	-	-
1011-2	Girls Bathroom by Room 16 @ B	SK	App	7.57	1/8/2020	-	-	-	None	-	-	-
1011-3	Girls Bathroom by Room 16 @ C	SK	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1012-1	Custodial Closet by Room 16	SS	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1013-1	Hallway by Cafeteria	WF	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1013-2	Hallway by Cafeteria	BF	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1014-1	Custodial Office Bathroom	SK	App	4.58	1/8/2020	-	-	-	None	-	-	-
1015-1	Mens Faculty Bathroom by Gym	SK	App	12.3	1/8/2020	-	-	-	None	-	-	-
1016-1	Nurses Office Bathroom	SK	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1017-1	Faculty Lounge	SK	App	1.37	1/8/2020	-	-	-	None	-	-	-
1017-2	Faculty Lounge	WF	App	25.1	1/8/2020				None	CAPPED		
1018-1	Womens Faculty Bathroom @ A	SK	App	1.14	1/8/2020	-	-	-	None	-	-	-
1018-2	Womens Faculty Bathroom @ B	SK	N/A		1/8/2020	-	-	-	None	SIGN	-	-
1019-1	Hallway by Room 7	WF	App	2.67	1/8/2020	-	-	-	None	-	-	-
1020-1	Room 8	SK	App	2.34	1/8/2020	-	-	-	None	-	-	-
1020-2	Room 8	WF	App	2	1/8/2020	-	-	-	None	-	-	-
1020-3	Room 8 Bathroom	SK	App	6.74	1/8/2020	-	-	-	None	-	-	-
1021-1	Room 10	SK	App	2.34	1/8/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1021-2	Room 10	WF	App	2.81	1/8/2020	-	-	-	None	-	-	-
1021-3	Room 10 Bathroom	SK	App	4.03	1/8/2020	-	-	-	None	-	-	-
1022-1	Room 12	SK	App	2.17	1/8/2020	-	-	-	None	-	-	-
1022-2	Room 12	WF	App	2.42	1/8/2020	-	-	-	None	-	-	-
1023-1	Room 14	SK	App	8.56	1/8/2020	-	-	-	None	-	-	-
1023-2	Room 14	WF	App	3.59	1/8/2020	-	-	-	None	-	-	-
1024-1	Room 13	SK	App	3.35	1/8/2020	-	-	-	None	-	-	-
1024-2	Room 13	WF	App	2.31	1/8/2020	-	-	-	None	-	-	-
1025-1	Room 11	SK	App	3.85	1/8/2020	-	-	-	None	-	-	-
1025-2	Room 11	WF	App	2.91	1/8/2020	-	-	-	None	-	-	-
1026-1	Room 9	SK	App	2.02	1/8/2020	-	-	-	None	-	-	-
1026-2	Room 9	WF	App	4.04	1/8/2020	-	-	-	None	-	-	-
1027-1	Room 7	SK	App	1.67	1/8/2020	-	-	-	None	-	-	-
1027-2	Room 7	WF	App	1.44	1/8/2020	-	-	-	None	-	-	-
1027-3	Room 7 Bathroom	SK	App	3.92	1/8/2020	-	-	-	None	-	-	-
1028-1	Girls Bathroom by Room 7 @ A	SK	App	10.8	1/8/2020	-	-	-	None	-	-	-
1028-2	Girls Bathroom by Room 7 @ B	SK	App	4.51	1/8/2020	-	-	-	None	-	-	-
1029-1	Boys Bathroom by Room 7 @ A	SK	App	10.6	1/8/2020	-	-	-	None	-	-	-
1029-2	Boys Bathroom by Room 7 @ B	SK	App	12.7	1/8/2020	-	-	-	None	-	-	-
1030-1	Custodial Closet by Room 7	SS	N/A		1/8/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1031-1	Room 5	SK	App	8.67	1/8/2020	-	-	-	None	-	-	-
1031-2	Room 5	WF	App	3.72	1/8/2020	-	-	-	None	-	-	-
1031-3	Room 5 Bathroom	SK	App	2.97	1/8/2020	-	-	-	None	-	-	-
1032-1	Room 3	SK	App	5.64	1/8/2020	-	-	-	None	-	-	-
1032-2	Room 3	WF	App	2.2	1/8/2020	-	-	-	None	-	-	-
1032-3	Room 3 Bathroom	SK	App	4.22	1/8/2020	-	-	-	None	-	-	-
1033-1	Room 1	SK	App	1.89	1/8/2020	-	-	-	None	-	-	-
1033-2	Room 1	WF	App	<1.0	1/8/2020	-	-	-	None	-	-	-
1033-3	Room 1 Bathroom	SK	App	3.67	1/8/2020	-	-	-	None	-	-	-
1034-1	Room 2 Bathroom	SK	App	4.03	1/8/2020	-	-	-	None	-	-	-
1034-2	Room 2	WF	App	44.1	1/8/2020				None	CAPPED		
1034-3	Room 2	SK	App	2.64	1/8/2020	-	-	-	None	-	-	-
1035-1	Room 4	SK	App	8.12	1/8/2020	-	-	-	None	-	-	-
1035-2	Room 4	WF	App	9.26	1/8/2020	-	-	-	None	-	-	-
1035-3	Room 4 Bathroom	SK	App	2.86	1/8/2020	-	-	-	None	-	-	-

Laboratory Report

NYE Report #: 2200090-13602

January 10, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Southdown Primary, Huntington, NY

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on January 08, 2020. New York Environmental analyzed the samples on January 09, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	08 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P133	1	Kitchen Handwash - SK; Initial	1.00	4.09	µg/L	
200108P134	2	Kitchen Dishwash Station @ A - SK; Initial	1.00	3.74	µg/L	
200108P135	3	Kitchen Dishwash Station @ B - SK; Initial	1.00	3.50	µg/L	
200108P136	4	Kitchen Spray - SY; Initial	1.00	5.41	µg/L	
200108P137	5	Kitchen Prep - SK; Initial	1.00	4.66	µg/L	
200108P138	6	Room 15 Bathroom - SK; Initial	1.00	2.24	µg/L	
200108P139	7	Room 16 - SK; Initial	1.00	3.78	µg/L	
200108P140	8	Room 16 - WF; Initial	1.00	5.59	µg/L	
200108P141	9	Room 17 - SK; Initial	1.00	9.90	µg/L	
200108P142	10	Room 18 - SK; Initial	1.00	4.43	µg/L	
200108P143	11	Room 18 - WF; Initial	1.00	2.11	µg/L	
200108P144	12	Room 19 - SK; Initial	1.00	9.78	µg/L	
200108P145	13	Room 19 - WF; Initial	1.00	8.78	µg/L	
200108P146	14	Room 21 - SK; Initial	1.00	4.56	µg/L	
200108P147	15	Room 21 - WF; Initial	1.00	4.34	µg/L	
200108P148	16	Room 22 - SK; Initial	1.00	3.19	µg/L	
200108P149	17	Room 22 - WF; Initial	1.00	6.03	µg/L	
200108P150	18	Boys Bathroom by Room 16 @ A - SK; Initial	1.00	3.38	µg/L	
200108P151	19	Boys Bathroom by Room 16 @ B - SK; Initial	1.00	4.07	µg/L	
200108P152	20	Girls Bathroom by Room 16 @ A - SK; Initial	1.00	8.02	µg/L	
200108P153	21	Girls Bathroom by Room 16 @ B - SK; Initial	1.00	7.57	µg/L	
200108P154	22	Hallway by Cafeteria - WF; Initial	1.00	<1.00	µg/L	
200108P155	23	Hallway by Cafeteria - BF; Initial	1.00	<1.00	µg/L	
200108P156	24	Custodian Office Bathroom - SK; Initial	1.00	4.58	µg/L	
200108P157	25	Mens Faculty Bathroom by Gym - SK; Initial	1.00	12.3	µg/L	
200108P158	26	Faculty Lounge - SK; Initial	1.00	1.37	µg/L	



Date Collected:	08 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P159	27	Faculty Lounge - WF; Initial	1.00	25.1	µg/L	H
200108P160	28	Women Faculty Bathroom @ A - SK; Initial	1.00	1.14	µg/L	
200108P161	29	Hallway by Room 7 - WF; Initial	1.00	2.67	µg/L	
200108P162	30	Room 8 - SK; Initial	1.00	2.34	µg/L	
200108P163	31	Room 8 - WF; Initial	1.00	2.00	µg/L	
200108P164	32	Room 8 Bathroom - SK; Initial	1.00	6.74	µg/L	
200108P165	33	Room 10 - SK; Initial	1.00	2.34	µg/L	
200108P166	34	Room 10 - WF; Initial	1.00	2.81	µg/L	
200108P167	35	Room 10 Bathroom - SK; Initial	1.00	4.03	µg/L	
200108P168	36	Room 12 - SK; Initial	1.00	2.17	µg/L	
200108P169	37	Room 12 - WF; Initial	1.00	2.42	µg/L	
200108P170	38	Room 14 - SK; Initial	1.00	8.56	µg/L	
200108P171	39	Room 14 - WF; Initial	1.00	3.59	µg/L	
200108P172	40	Room 13 - SK; Initial	1.00	3.35	µg/L	
200108P173	41	Room 13 - WF; Initial	1.00	2.31	µg/L	
200108P174	42	Room 11 - SK; Initial	1.00	3.85	µg/L	
200108P175	43	Room 11 - WF; Initial	1.00	2.91	µg/L	
200108P176	44	Room 9 - SK; Initial	1.00	2.02	µg/L	
200108P177	45	Room 9 - WF; Initial	1.00	4.04	µg/L	
200108P178	46	Room 7 - SK; Initial	1.00	1.67	µg/L	
200108P179	47	Room 7 - WF; Initial	1.00	1.44	µg/L	
200108P180	48	Room 7 Bathroom - SK; Initial	1.00	3.92	µg/L	
200108P181	49	Girls Bathroom by Room 7 @ A - SK; Initial	1.00	10.8	µg/L	
200108P182	50	Girls Bathroom by Room 7 @ B - SK; Initial	1.00	4.51	µg/L	
200108P183	51	Boys Bathroom by Room 7 @ A - SK; Initial	1.00	10.6	µg/L	
200108P184	52	Boys Bathroom by Room 7 @ B - SK; Initial	1.00	12.7	µg/L	
200108P185	53	Room 5 - SK; Initial	1.00	8.67	µg/L	



Date Collected:	08 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P186	54	Room 5 - WF; Initial	1.00	3.72	µg/L	
200108P187	55	Room 5 Bathroom - SK; Initial	1.00	2.97	µg/L	
200108P188	56	Room 3 - SK; Initial	1.00	5.64	µg/L	
200108P189	57	Room 3 - WF; Initial	1.00	2.20	µg/L	
200108P190	58	Room 3 Bathroom - SK; Initial	1.00	4.22	µg/L	
200108P191	59	Room 1 - SK; Initial	1.00	1.89	µg/L	
200108P192	60	Room 1 - WF; Initial	1.00	<1.00	µg/L	
200108P193	61	Room 1 Bathroom - SK; Initial	1.00	3.67	µg/L	
200108P194	62	Room 2 Bathroom - SK; Initial	1.00	4.03	µg/L	
200108P195	63	Room 2 - WF; Initial	1.00	44.1	µg/L	H
200108P196	64	Room 2 - SK; Initial	1.00	2.64	µg/L	
200108P197	65	Room 4 - SK; Initial	1.00	8.12	µg/L	
200108P198	66	Room 4 - WF; Initial	1.00	9.26	µg/L	
200108P199	67	Room 4 Bathroom - SK; Initial	1.00	2.86	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2200707-13949

February 14, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Southdown Primary School, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 14, 2020. New York Environmental analyzed the samples on February 14, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	12 Feb 2020
Date Received:	14 Feb 2020
Date Analyzed:	14 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
200214K001	1	Room 2 - WF; Initial	1.00	96.0	µg/L	E,H

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.



Appendix D

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen Dishwash Station @ A	SK	App	2.67	1/7/2020	-	-	-	None	-	-	-
1001-2	Kitchen Dishwash Station @ B	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1001-3	Kitchen Dishwash Station	SPY	App	2.38	1/7/2020	-	-	-	None	-	-	-
1001-4	Kitchen Handwash	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1002-1	Room 15 Bathroom	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1003-1	Girls Bathroom by Room 16 @ A	SK	App	1.12	1/7/2020	-	-	-	None	-	-	-
1003-2	Girls Bathroom by Room 16 @ B	SK	N/A		1/7/2020	-	-	-	None	SIGN	-	-
1003-3	Girls Bathroom by Room 16 @ C	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1004-1	Custodian Closet 3	SK	N/A		1/7/2020	-	-	-	None	SIGN	-	-
1005-1	Room 16	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1005-2	Room 16	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1006-1	Boys Bathroom by Room 16 @ A	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1006-2	Boys Bathroom by Room 16 @ B	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1006-3	Boys Bathroom by Room 16 @ C	SK	N/A		1/7/2020	-	-	-	None	SIGN	-	-
1007-1	Hallway by Room 17	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1008-1	Room 17	SK	App	1.08	1/7/2020	-	-	-	None	-	-	-
1008-2	Room 17	WF	App	1.51	1/7/2020	-	-	-	None	-	-	-
1009-1	Room 18	SK	App	1.84	1/7/2020	-	-	-	None	-	-	-
1009-2	Room 18	WF	App	2.08	1/7/2020	-	-	-	None	-	-	-
1010-1	Room 19	SK	App	3.44	1/7/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1010-2	Room 19	WF	App	1.38	1/7/2020	-	-	-	None	-	-	-
1011-1	Room 22	SK	App	1.86	1/7/2020	-	-	-	None	-	-	-
1011-2	Room 22	WF	App	1.67	1/7/2020	-	-	-	None	-	-	-
1012-1	Room 21	SK	App	3.85	1/7/2020	-	-	-	None	-	-	-
1012-2	Room 21	WF	App	1.85	1/7/2020	-	-	-	None	-	-	-
1013-1	Hallway by Cafeteria	WF	App	1.65	1/7/2020	-	-	-	None	-	-	-
1014-1	Faculty Bathroom by Custodian Office	SK	N/A		1/7/2020	-	-	-	None	SIGN	-	-
1015-1	Custodian Office Bathroom	SK	App	3.97	1/7/2020	-	-	-	None	-	-	-
1016-1	Nurse's Office Bathroom	SK	N/A		1/7/2020	-	-	-	None	SIGN	-	-
1017-1	Faculty Lounge	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1018-1	Women Faculty Bathroom @ A	SK	N/A		1/7/2020	-	-	-	None	SIGN	-	-
1018-2	Women Faculty Bathroom @ B	SK	N/A		1/7/2020	-	-	-	None	SIGN	-	-
1019-1	Hallway by Room 8	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1020-1	Room 7	SK	App	1.66	1/7/2020	-	-	-	None	-	-	-
1020-2	Room 7	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1020-3	Room 7 Bathroom	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1021-1	Room 5	SK	App	1.67	1/7/2020	-	-	-	None	-	-	-
1021-2	Room 5	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1021-3	Room 5 Bathroom	SK	App	5.07	1/7/2020	-	-	-	None	-	-	-
1022-1	Room 3	SK	App	1.82	1/7/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1022-2	Room 3	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1022-3	Room 3 Bathroom	SK	App	6.52	1/7/2020	-	-	-	None	-	-	-
1023-1	Room 1	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1023-2	Room 1	WF	App	3.26	1/7/2020	-	-	-	None	-	-	-
1023-3	Room 1 Bathroom	SK	App	3.3	1/7/2020	-	-	-	None	-	-	-
1024-1	Room 2 Bathroom	SK	App	1.43	1/7/2020	-	-	-	None	-	-	-
1024-2	Room 2	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1024-3	Room 2	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1025-1	Room 4	SK	App	3.36	1/7/2020	-	-	-	None	-	-	-
1025-2	Room 4	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1025-3	Room 4 Bathroom	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1026-1	Room 6	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1026-2	Room 6	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1026-3	Room 6 Bathroom	SK	App	1.17	1/7/2020	-	-	-	None	-	-	-
1027-1	Room 8	SK	App	1.02	1/7/2020	-	-	-	None	-	-	-
1027-2	Room 8	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1027-3	Room 8 Bathroom	SK	App	3.84	1/7/2020	-	-	-	None	-	-	-
1028-1	Girls Bathroom by Room 8 @ A	SK	App	1.42	1/7/2020	-	-	-	None	-	-	-
1028-2	Girls Bathroom by Room 8 @ B	SK	App	1.33	1/7/2020	-	-	-	None	-	-	-
1029-1	Custodian Closet by Room 8	SK	N/A		1/7/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1030-1	Boys Bathroom by Room 8 @ A	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1030-2	Boys Bathroom by Room 8 @ B	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1031-1	Room 10	SK	App	1.12	1/7/2020	-	-	-	None	-	-	-
1031-2	Room 10	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1032-1	Room 12	SK	App	1.02	1/7/2020	-	-	-	None	-	-	-
1032-2	Room 12	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1033-1	Room 14	SK	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1033-2	Room 14	WF	App	<1.0	1/7/2020	-	-	-	None	-	-	-
1034-1	Room 13	SK	App	9.22	1/7/2020	-	-	-	None	-	-	-
1034-2	Room 13	WF	App	2.1	1/7/2020	-	-	-	None	-	-	-
1035-1	Room 11	SK	App	2	1/7/2020	-	-	-	None	-	-	-
1035-2	Room 11	WF	App	1.05	1/7/2020	-	-	-	None	-	-	-

Laboratory Report

NYE Report #: 2200089-13601

January 10, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Washington Primary, Huntington, NY

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on January 08, 2020. New York Environmental analyzed the samples on January 09, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	07 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P069	1	Kitchen Dishwash Station @ A - SK; Initial	1.00	2.67	µg/L	
200108P070	2	Kitchen Dishwash Station @ B - SK; Initial	1.00	<1.00	µg/L	
200108P071	3	Kitchen Dishwash Station - SPY; Initial	1.00	2.38	µg/L	
200108P072	4	Kitchen Handwash - SK; Initial	1.00	<1.00	µg/L	
200108P073	5	Room 15 Bathroom - SK; Initial	1.00	<1.00	µg/L	
200108P074	6	Girls Bathroom by Room 16 @ A - SK; Initial	1.00	1.12	µg/L	
200108P075	7	Girls Bathroom by Room 16 @ C - SK; Initial	1.00	<1.00	µg/L	
200108P076	8	Room 16 - SK; Initial	1.00	<1.00	µg/L	
200108P077	9	Room 16 - WF; Initial	1.00	<1.00	µg/L	
200108P078	10	Boys Bathroom by Room 16 @ A - SK; Initial	1.00	<1.00	µg/L	
200108P079	11	Boys Bathroom by Room 16 @ B - SK; Initial	1.00	<1.00	µg/L	
200108P080	12	Hallway by Room 17 - WF; Initial	1.00	<1.00	µg/L	
200108P081	13	Room 17 - SK; Initial	1.00	1.08	µg/L	
200108P082	14	Room 17 - WF; Initial	1.00	1.51	µg/L	
200108P083	15	Room 18 - SK; Initial	1.00	1.84	µg/L	
200108P084	16	Room 18 - WF; Initial	1.00	2.08	µg/L	
200108P085	17	Room 19 - SK; Initial	1.00	3.44	µg/L	
200108P086	18	Room 19 - WF; Initial	1.00	1.38	µg/L	
200108P087	19	Room 22 - SK; Initial	1.00	1.86	µg/L	
200108P088	20	Room 22 - WF; Initial	1.00	1.67	µg/L	
200108P089	21	Room 21 - SK; Initial	1.00	3.85	µg/L	
200108P090	22	Room 21 - WF; Initial	1.00	1.85	µg/L	
200108P091	23	Hallway by Cafeteria - WF; Initial	1.00	1.65	µg/L	
200108P092	24	Custodian Office Bathroom - SK; Initial	1.00	3.97	µg/L	
200108P093	25	Faculty Lounge - SK; Initial	1.00	<1.00	µg/L	
200108P094	26	Hallway by Room 8 - WF; Initial	1.00	<1.00	µg/L	



Date Collected:	07 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P095	27	Room 7 - SK; Initial	1.00	1.66	µg/L	
200108P096	28	Room 7 - WF; Initial	1.00	<1.00	µg/L	
200108P097	29	Room 7 Bathroom - SK; Initial	1.00	<1.00	µg/L	
200108P098	30	Room 5 - SK; Initial	1.00	1.67	µg/L	
200108P099	31	Room 5 - WF; Initial	1.00	<1.00	µg/L	
200108P100	32	Room 5 Bathroom - SK; Initial	1.00	5.07	µg/L	
200108P101	33	Room 3 - SK; Initial	1.00	1.82	µg/L	
200108P102	34	Room 3 - WF; Initial	1.00	<1.00	µg/L	
200108P103	35	Room 3 Bathroom - SK; Initial	1.00	6.52	µg/L	
200108P104	36	Room 1 - SK; Initial	1.00	<1.00	µg/L	
200108P105	37	Room 1 - WF; Initial	1.00	3.26	µg/L	
200108P106	38	Room 1 Bathroom - SK; Initial	1.00	3.30	µg/L	
200108P107	39	Room 2 Bathroom - SK; Initial	1.00	1.43	µg/L	
200108P108	40	Room 2 - WF; Initial	1.00	<1.00	µg/L	
200108P109	41	Room 2 - SK; Initial	1.00	<1.00	µg/L	
200108P110	42	Room 4 - SK; Initial	1.00	3.36	µg/L	
200108P111	43	Room 4 - WF; Initial	1.00	<1.00	µg/L	
200108P112	44	Room 4 Bathroom - SK; Initial	1.00	<1.00	µg/L	
200108P113	45	Room 6 - SK; Initial	1.00	<1.00	µg/L	
200108P114	46	Room 6 - WF; Initial	1.00	<1.00	µg/L	
200108P115	47	Room 6 Bathroom - SK; Initial	1.00	1.17	µg/L	
200108P116	48	Room 8 - SK; Initial	1.00	1.02	µg/L	
200108P117	49	Room 8 - WF; Initial	1.00	<1.00	µg/L	
200108P118	50	Room 8 Bathroom - SK; Initial	1.00	3.84	µg/L	
200108P119	51	Girls Bathroom by Room 8 @ A - SK; Initial	1.00	1.42	µg/L	
200108P120	52	Girls Bathroom by Room 8 @ B - SK; Initial	1.00	1.33	µg/L	
200108P121	53	Boys Bathroom by Room 8 @ A - SK; Initial	1.00	<1.00	µg/L	



Date Collected:	07 Jan 2020
Date Received:	08 Jan 2020
Date Analyzed:	09 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200108P122	54	Boys Bathroom by Room 8 @ B - SK; Initial	1.00	<1.00	µg/L	
200108P123	55	Room 10 - SK; Initial	1.00	1.12	µg/L	
200108P124	56	Room 10 - WF; Initial	1.00	<1.00	µg/L	
200108P125	57	Room 12 - SK; Initial	1.00	1.02	µg/L	
200108P126	58	Room 12 - WF; Initial	1.00	<1.00	µg/L	
200108P127	59	Room 14 - SK; Initial	1.00	<1.00	µg/L	
200108P128	60	Room 14 - WF; Initial	1.00	<1.00	µg/L	
200108P129	61	Room 13 - SK; Initial	1.00	9.22	µg/L	
200108P130	62	Room 13 - WF; Initial	1.00	2.10	µg/L	
200108P131	63	Room 11 - SK; Initial	1.00	2.00	µg/L	
200108P132	64	Room 11 - WF; Initial	1.00	1.05	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

LOQ: Limit of Quantitation



Appendix E

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2001-1	Kitchen Handwash @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
2001-2	Kitchen Food Prep @ A	SK	App	4.01	1/10/2020	-	-	-	None	-	-	-
2001-3	Kitchen Warewashing @ A	SK	App	2.18	1/10/2020	-	-	-	None	-	-	-
2001-4	Kitchen Warewashing @ B	SPY	App	2.15	1/10/2020	-	-	-	None	-	-	-
2001-5	Kitchen Warewashing @ C	SK	App	1.1	1/10/2020	-	-	-	None	-	-	-
2001-6	Kitchen Island	SK	App	1.11	1/10/2020	-	-	-	None	-	-	-
2001-7	Kitchen Potfiller North	SK	App	6.5	1/10/2020	-	-	-	None	-	-	-
2001-8	Kitchen Handwash @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
2001-9	Kitchen by Dishwasher	SK	App	1.23	1/10/2020	-	-	-	None	-	-	-
2001-10	Kitchen Food Prep @ B	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
2001-11	Kitchen Potfiller South	SK	App	9.12	1/10/2020	-	-	-	None	-	-	-
2001-12	Kitchen Serving Line North	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
2001-13	Kitchen Serving Line South	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
2001-14	Kitchen Bathroom	SK	App	4.12	1/10/2020	-	-	-	None	-	-	-
2002-1	Cafeteria	WF	App	<1.0	1/10/2020	-	-	-	None	-	-	-
2003-1	Custodial Closet by Custodial Office	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
2004-1	Room 211	SK	App	7.03	1/10/2020	-	-	-	None	-	-	-
2004-1	Room 211	WF	App	5.45	1/10/2020	-	-	-	None	-	-	-
2005-1	Room 209	SK	App	4.5	1/10/2020	-	-	-	None	-	-	-
2005-1	Room 209	WF	App	5.12	1/10/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2006-1	Boys Bathroom by Room 210 - Mens Faculty	SK	App	1.48	1/10/2020	-	-	-	None	-	-	-
2006-2	Boys Bathroom by Room 210 @ A	SK	App	4.42	1/10/2020	-	-	-	None	-	-	-
2006-3	Boys Bathroom by Room 210 @ B	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
2006-4	Boys Bathroom by Room 210 @ C	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
2006-5	Boys Bathroom by Room 210 @ D	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
2007-1	Custodial Closet by Room 210	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
2008-1	Girls Bathroom by Room 210 - Womens Faculty	SK	App	3.44	1/10/2020	-	-	-	None	-	-	-
2008-2	Girls Bathroom by Room 210 @ A	SK	App	5.62	1/10/2020	-	-	-	None	-	-	-
2008-3	Girls Bathroom by Room 210 @ B	SK	App	13.3	1/10/2020	-	-	-	None	-	-	-
2008-4	Girls Bathroom by Room 210 @ C	SK	App	12.8	2/27/2020	-	-	-	None	-	-	-
2008-5	Girls Bathroom by Room 210 @ D	SK	App	1.48	1/10/2020	-	-	-	None	-	-	-
2008-6	Girls Bathroom by Room 210 @ E	SK	App	2.95	1/10/2020	-	-	-	None	-	-	-
2009-1	Room 207	SK	App	9.26	1/10/2020	-	-	-	None	-	-	-
2009-2	Room 207	WF	App	3.62	1/10/2020	-	-	-	None	-	-	-
2010-1	Room 205	SK	App	6.96	1/10/2020	-	-	-	None	-	-	-
2010-2	Room 205	WF	App	8.29	1/10/2020	-	-	-	None	-	-	-
2011-1	Room 203	SK	App	7.71	2/27/2020	-	-	-	None	-	-	-
2011-2	Room 203	WF	N/A		1/10/2020	-	-	-	None	SIGN	-	-
2012-1	Room 201	SK	App	3.72	2/27/2020	-	-	-	None	-	-	-
2012-2	Room 201	WF	App	4.13	1/10/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2013-1	Room 202	SK	App	8.84	2/27/2020	-	-	-	None	-	-	-
2013-2	Room 202	WF	App	10.9	1/10/2020	-	-	-	None	-	-	-
2014-1	STEM Director K-12	SK	App	7.69	2/27/2020	-	-	-	None	-	-	-
2015-1	Room 204	SK	App	3.36	1/10/2020	-	-	-	None	-	-	-
2015-2	Room 204	WF	App	3.87	1/10/2020	-	-	-	None	-	-	-
2016-1	Room 206	SK	App	6.14	1/10/2020	-	-	-	None	-	-	-
2016-2	Room 206	WF	App	4.44	1/10/2020	-	-	-	None	-	-	-
2017-1	Room 208	SK	App	3.47	1/10/2020	-	-	-	None	-	-	-
2017-2	Room 208	WF	App	5.2	1/10/2020	-	-	-	None	-	-	-
2018-1	Room 210	SK	App	14	3/13/2020	-	-	-	None	-	-	-
2018-2	Room 210	WF	App	6.18	2/27/2020	-	-	-	None	-	-	-
2019-1	Girls Bathroom by Room 213 @ A	SK	App	5.93	1/10/2020	-	-	-	None	-	-	-
2019-2	Girls Bathroom by Room 213 @ B	SK	App	<1.0	2/27/2020	-	-	-	None	-	-	-
2020-1	Boys Bathroom by Room 213 @ A	SK	App	1.94	1/10/2020	-	-	-	None	-	-	-
2020-2	Boys Bathroom by Room 213 @ B	SK	App	2.66	1/10/2020	-	-	-	None	-	-	-
2021-1	Room 214	SK	App	2.81	1/10/2020	-	-	-	None	-	-	-
2021-2	Room 214	WF	App	2.09	1/10/2020	-	-	-	None	-	-	-
2022-1	Room 216	SK	App	1.21	1/10/2020	-	-	-	None	-	-	-
2022-2	Room 216	WF	App	1.69	1/10/2020	-	-	-	None	-	-	-
2023-1	Room 218	SK	App	1.19	1/10/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2023-2	Room 218	WF	App	2.91	1/10/2020	-	-	-	None	-	-	-
2024-1	Room 220	SK	App	4.82	1/10/2020	-	-	-	None	-	-	-
2024-2	Room 220	WF	App	1.95	1/10/2020	-	-	-	None	-	-	-
2025-1	Room 221	SK	App	2.51	1/10/2020	-	-	-	None	-	-	-
2025-2	Room 221	WF	App	2.03	1/10/2020	-	-	-	None	-	-	-
2026-1	Mens Bathroom by Room 221	SK	App	6.73	1/10/2020	-	-	-	None	-	-	-
2027-1	Custodial Closet by Room 221	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
2028-1	Womens Bathroom by Room 221	SK	App	4.94	1/10/2020	-	-	-	None	-	-	-
2029-1	Room 219	SK	App	13	1/10/2020	-	-	-	None	-	-	-
2029-2	Room 219	WF	App	3.76	1/10/2020	-	-	-	None	-	-	-
2030-1	Room 217	SK	App	13.4	1/10/2020	-	-	-	None	-	-	-
2030-2	Room 217	WF	App	5.42	1/10/2020	-	-	-	None	-	-	-
2031-1	Room 215	SK	App	8.31	1/10/2020	-	-	-	None	-	-	-
2031-2	Room 215	WF	App	8.29	1/10/2020	-	-	-	None	-	-	-
2032-1	Room 213	SK	App	2.44	1/10/2020	-	-	-	None	-	-	-
2032-2	Room 213	WF	App	4.95	1/10/2020	-	-	-	None	-	-	-
1001-1	Boiler Room Bathroom	SK	App	1.26	1/10/2020	-	-	-	None	-	-	-
1002-1	Custodial Closet by Boiler Room	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1003-1	Bathroom by Superintendent	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1004-1	Administration Breakroom	SK	App	5.86	2/27/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1004-2	Administration Breakroom	WF	App	86.8	1/10/2020					CAPPED		
1005-1	Assistant Superintendent	SK	App	2.42	1/10/2020	-	-	-	None	-	-	-
1005-2	Assistant Superintendent	WF	N/A		1/10/2020	-	-	-	None	CAPPED	-	-
1006-1	Transportation	SK	App	5.49	1/10/2020	-	-	-	None	-	-	-
1006-2	Transportation	WF	N/A		1/10/2020	-	-	-	None	CAPPED	-	-
1007-1	Treasurer	SK	App	4.76	1/10/2020	-	-	-	None	-	-	-
1007-2	Treasurer	WF	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1008-1	Human Resources	SK	App	3.09	1/10/2020	-	-	-	None	-	-	-
1008-2	Human Resources	WF	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1009-1	Room 125	SK	App	2.17	1/10/2020	-	-	-	None	-	-	-
1010-1	Girls Bathroom by Music Room	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1011-1	Hallway by Book Storage	WF	App	1.84	1/10/2020	-	-	-	None	-	-	-
1012-1	Boys Bathroom by Book Storage	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1013-1	Room 110 Counter @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1013-2	Room 110 Counter @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1014-1	Gym	WF	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1015-1	Room 112 Unit 1 @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1015-2	Room 112 Unit 1 @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1015-3	Room 112 Unit 1 @ C	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1015-4	Room 112 Unit 2 @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1015-5	Room 112 Unit 2 @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1015-6	Room 112 Unit 2 @ C	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1016-1	Custodial Closet by Auditorium	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1017-1	Womens Bathroom by Gym	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1018-1	Mens Bathroom by Gym	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1019-1	Girls Locker Room	WF	App	23.7	3/13/2020				None	CAPPED		
1019-2	Girls Locker Room @ A	SK	App	3.84	3/13/2020	-	-	-	None	-	-	-
1019-3	Girls Locker Room @ B	SK	App	4.93	1/10/2020	-	-	-	None	-	-	-
1020-1	Boys Locker Room	SK	App	4.26	2/27/2020	-	-	-	None	-	-	-
1020-2	Boys Locker Room	WF	App	11.4	2/27/2020	-	-	-	None	-	-	-
1021-1	Hallway by Main Office	BF	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1021-2	Hallway by Main Office	WF	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1022-1	Main Office Bathroom	SK	App	8.45	1/10/2020	-	-	-	None	-	-	-
1023-1	Nurses Office	SK	App	1.5	1/10/2020	-	-	-	None	-	-	-
1023-2	Nurses Office Bathroom	SK	App	7.68	1/10/2020	-	-	-	None	-	-	-
1025-1	Hallway by Room 122	WF	App	1.15	1/10/2020	-	-	-	None	-	-	-
1026-1	Girls Bathroom by Room 118	SK	App	1.84	1/10/2020	-	-	-	None	-	-	-
1024-1	Room 118	SK	App	14.7	1/10/2020	-	-	-	None	-	-	-
1025-1	Room 118	WF	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1026-1	Room 118 Bathroom	SK	App	6.09	1/10/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1027-1	Room 117	SK	App	6.68	1/10/2020	-	-	-	None	-	-	-
1027-2	Room 117	WF	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1027-3	Room 117 Bathroom	SK	App	3.67	2/27/2020	-	-	-	None	-	-	-
1028-1	Custodial Closet by Room 117	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1029-1	Room 116	SK	App	7.81	1/10/2020	-	-	-	None	-	-	-
1029-2	Room 116	WF	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1029-3	Room 116 Bathroom	SK	App	11.5	1/10/2020	-	-	-	None	-	-	-
1030-1	Room 115	SK	App	12.6	1/10/2020	-	-	-	None	-	-	-
1030-2	Room 115	WF	App	12.3	1/10/2020	-	-	-	None	-	-	-
1030-3	Room 115 Bathroom	SK	App	12.4	1/10/2020	-	-	-	None	-	-	-
1031-1	Room 114	SK	App	13.1	1/10/2020	-	-	-	None	-	-	-
1031-2	Room 114	WF	App	3.08	2/27/2020	-	-	-	None	-	-	-
1031-3	Room 114 Bathroom	SK	App	11.1	1/10/2020	-	-	-	None	-	-	-

Laboratory Report

NYE Report #: 2200174-13636

January 13, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Jack Abrams Stem Magnet Intermediate School; Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on January 10, 2020. New York Environmental analyzed the samples on January 11, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	10 Jan 2020
Date Received:	10 Jan 2020
Date Analyzed:	11 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200110P051	1	Kitchen Food Prep @ A - SK; Initial	1.00	4.01	µg/L	
200110P052	2	Kitchen Warewashing @ A - SK; Initial	1.00	2.18	µg/L	
200110P053	3	Kitchen Warewashing @ B - SPY; Initial	1.00	2.15	µg/L	
200110P054	4	Kitchen Warewashing @ C - SK; Initial	1.00	1.10	µg/L	
200110P055	5	Kitchen Island - SK; Initial	1.00	1.11	µg/L	
200110P056	6	Kitchen Potfiller North - SK; Initial	1.00	6.50	µg/L	
200110P057	7	Kitchen by Dishwasher - SK; Initial	1.00	1.23	µg/L	
200110P058	8	Kitchen Food Prep @ B - SK; Initial	1.00	<1.00	µg/L	
200110P059	9	Kitchen Potfiller South - SK; Initial	1.00	9.12	µg/L	
200110P060	10	Kitchen Bathroom - SK; Initial	1.00	4.12	µg/L	
200110P061	11	Cafeteria - WF; Initial	1.00	<1.00	µg/L	
200110P062	12	Room 211 - SK; Initial	1.00	7.03	µg/L	
200110P063	13	Room 211 - WF; Initial	1.00	5.45	µg/L	
200110P064	14	Room 209 - SK; Initial	1.00	4.50	µg/L	
200110P065	15	Room 209 - WF; Initial	1.00	5.12	µg/L	
200110P066	16	Boys Bathroom by Room 210 - Mens Faculty - SK; Initial	1.00	1.48	µg/L	
200110P067	17	Boys Bathroom by Room 210 @ A - SK; Initial	1.00	4.42	µg/L	
200110P068	18	Boys Bathroom by Room 210 @ B - SK; Initial	1.00	<1.00	µg/L	
200110P069	19	Boys Bathroom by Room 210 @ C - SK; Initial	1.00	<1.00	µg/L	
200110P070	20	Boys Bathroom by Room 210 @ D - SK; Initial	1.00	<1.00	µg/L	
200110P071	21	Girls Bathroom by Room 210 - Womens Faculty - SK; Initial	1.00	3.44	µg/L	
200110P072	22	Girls Bathroom by Room 210 @ A - SK; Initial	1.00	5.62	µg/L	
200110P073	23	Girls Bathroom by Room 210 @ B - SK; Initial	1.00	13.3	µg/L	
200110P074	24	Girls Bathroom by Room 210 @ C - SK; Initial	1.00	15.2	µg/L	H
200110P075	25	Girls Bathroom by Room 210 @ D - SK; Initial	1.00	1.48	µg/L	
200110P076	26	Girls Bathroom by Room 210 @ E - SK; Initial	1.00	2.95	µg/L	



Date Collected:	10 Jan 2020
Date Received:	10 Jan 2020
Date Analyzed:	11 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200110P077	27	Room 207 - SK; Initial	1.00	9.26	µg/L	
200110P078	28	Room 207 - WF; Initial	1.00	3.62	µg/L	
200110P079	29	Room 205 - SK; Initial	1.00	6.96	µg/L	
200110P080	30	Room 205 - WF; Initial	1.00	8.29	µg/L	
200110P081	31	Room 203 - SK; Initial	1.00	312	µg/L	E,H
200110P082	32	Room 201 - SK; Initial	1.00	15.8	µg/L	H
200110P083	33	Room 201 - WF; Initial	1.00	4.13	µg/L	
200110P084	34	Room 202 - SK; Initial	1.00	22.3	µg/L	H
200110P085	35	Room 202 - WF; Initial	1.00	10.9	µg/L	
200110P086	36	STEM Director K-12 - SK; Initial	1.00	26.6	µg/L	H
200110P087	37	Room 204 - SK; Initial	1.00	3.36	µg/L	
200110P088	38	Room 204 - WF; Initial	1.00	3.87	µg/L	
200110P089	39	Room 206 - SK; Initial	1.00	6.14	µg/L	
200110P090	40	Room 206 - WF; Initial	1.00	4.44	µg/L	
200110P091	41	Room 208 - SK; Initial	1.00	3.47	µg/L	
200110P092	42	Room 208 - WF; Initial	1.00	5.20	µg/L	
200110P093	43	Room 210 - SK; Initial	1.00	270	µg/L	E,H
200110P094	44	Room 210 - WF; Initial	1.00	33.0	µg/L	H
200110P095	45	Girls Bathroom by Room 213 @ A - SK; Initial	1.00	5.93	µg/L	
200110P096	46	Girls Bathroom by Room 213 @ B - SK; Initial	1.00	31.9	µg/L	H
200110P097	47	Boys Bathroom by Room 213 @ A - SK; Initial	1.00	1.94	µg/L	
200110P098	48	Boys Bathroom by Room 213 @ B - SK; Initial	1.00	2.66	µg/L	
200110P099	49	Room 214 - SK; Initial	1.00	2.81	µg/L	
200110P100	50	Room 214 - WF; Initial	1.00	2.09	µg/L	
200110P101	51	Room 216 - SK; Initial	1.00	1.21	µg/L	
200110P102	52	Room 216 - WF; Initial	1.00	1.69	µg/L	
200110P103	53	Room 218 - SK; Initial	1.00	1.19	µg/L	



Date Collected:	10 Jan 2020
Date Received:	10 Jan 2020
Date Analyzed:	11 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200110P104	54	Room 218 - WF; Initial	1.00	2.91	µg/L	
200110P105	55	Room 220 - SK; Initial	1.00	4.82	µg/L	
200110P106	56	Room 220 - WF; Initial	1.00	1.95	µg/L	
200110P107	57	Room 221 - SK; Initial	1.00	2.51	µg/L	
200110P108	58	Room 221 - WF; Initial	1.00	2.03	µg/L	
200110P109	59	Mens Bathroom by Room 221 - SK; Initial	1.00	6.73	µg/L	
200110P110	60	Womens Bathroom by Room 221 - SK; Initial	1.00	4.94	µg/L	
200110P111	61	Room 219 - SK; Initial	1.00	13.0	µg/L	
200110P112	62	Room 219 - WF; Initial	1.00	3.76	µg/L	
200110P113	63	Room 217 - SK; Initial	1.00	13.4	µg/L	
200110P114	64	Room 217 - WF; Initial	1.00	5.42	µg/L	
200110P115	65	Room 215 - SK; Initial	1.00	8.31	µg/L	
200110P116	66	Room 215 - WF; Initial	1.00	8.29	µg/L	
200110P117	67	Room 213 - SK; Initial	1.00	2.44	µg/L	
200110P118	68	Room 213 - WF; Initial	1.00	4.95	µg/L	
200110P119	69	Boiler Room Bathroom - SK; Initial	1.00	1.26	µg/L	
200110P120	70	Administration Breakroom - SK; Initial	1.00	5.86	µg/L	
200110P121	71	Administration Breakroom - WF; Initial	1.00	86.8	µg/L	E,H
200110P122	72	Assistant Superintendent - SK; Initial	1.00	91.0	µg/L	E,H
200110P123	73	Transportation - SK; Initial	1.00	5.49	µg/L	
200110P124	74	Treasurer - SK; Initial	1.00	4.76	µg/L	
200110P125	75	Human Resources - SK; Initial	1.00	3.09	µg/L	
200110P126	76	Room 125 - SK; Initial	1.00	2.17	µg/L	
200110P127	77	Hallway by Book Storage - WF; Initial	1.00	1.84	µg/L	
200110P128	78	Gym - WF; Initial	1.00	<1.00	µg/L	
200110P129	79	Girls Locker Room - WF; Initial	1.00	77.2	µg/L	E,H
200110P130	80	Girls Locker Room @ A - SK; Initial	1.00	21.6	µg/L	H



Date Collected:	10 Jan 2020
Date Received:	10 Jan 2020
Date Analyzed:	11 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200110P131	81	Girls Locker Room @ B - SK; Initial	1.00	4.93	µg/L	
200110P132	82	Boys Locker Room - SK; Initial	1.00	81.8	µg/L	E,H
200110P133	83	Boys Locker Room - WF; Initial	1.00	30.4	µg/L	H
200110P134	84	Hallway by Main Office - BF; Initial	1.00	<1.00	µg/L	
200110P135	85	Hallway by Main Office - WF; Initial	1.00	<1.00	µg/L	
200110P136	86	Main Office Bathroom - SK; Initial	1.00	8.45	µg/L	
200110P137	87	Nurses Office - SK; Initial	1.00	1.50	µg/L	
200110P138	88	Nurses Office Bathroom - SK; Initial	1.00	7.68	µg/L	
200110P139	89	Hallway by Room 122 - WF; Initial	1.00	1.15	µg/L	
200110P140	90	Girls Bathroom by Room 118 - SK; Initial	1.00	1.84	µg/L	
200110P141	91	Room 118 - SK; Initial	1.00	14.7	µg/L	
200110P142	92	Room 118 Bathroom - SK; Initial	1.00	6.09	µg/L	
200110P143	93	Room 117 - SK; Initial	1.00	6.68	µg/L	
200110P144	94	Room 117 Bathroom - SK; Initial	1.00	15.9	µg/L	H
200110P145	95	Room 116 - SK; Initial	1.00	7.81	µg/L	
200110P146	96	Room 116 Bathroom - SK; Initial	1.00	11.5	µg/L	
200110P147	97	Room 115 - SK; Initial	1.00	12.6	µg/L	
200110P148	98	Room 115 - WF; Initial	1.00	12.3	µg/L	
200110P149	99	Room 115 Bathroom - SK; Initial	1.00	12.4	µg/L	
200110P150	100	Room 114 - SK; Initial	1.00	13.1	µg/L	
200110P151	101	Room 114 - WF; Initial	1.00	17.7	µg/L	H
200110P152	102	Room 114 Bathroom - SK; Initial	1.00	11.1	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2200949-14086

March 2, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Jack Abrams Stem Magnet Intermediate School Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 27, 2020. New York Environmental analyzed the samples on February 28, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	27 Feb 2020
Date Received:	27 Feb 2020
Date Analyzed:	28 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200227O006	1	Boy's Locker Room-WF; Initial	1.00	11.4	µg/L	
200227O007	2	Boy's Locker Room-SK; Initial	1.00	4.26	µg/L	
200227O008	3	Girl's Locker Rom-WF; Initial	1.00	23.7	µg/L	H
200227O009	4	Girl's Locker Room @A-SK; Initial	1.00	24.4	µg/L	H
200227O010	5	Room 114-WF; Initial	1.00	3.08	µg/L	
200227O011	6	Room 117 Bathroom-SK; Initial	1.00	3.67	µg/L	
200227O012	7	Assistant Superintendent-SK; Initial	1.00	2.42	µg/L	
200227O013	8	Room 201-SK; Initial	1.00	3.72	µg/L	
200227O014	9	STEM Director K-12-SK; Initial	1.00	7.69	µg/L	
200227O015	10	Room 203-SK; Initial	1.00	7.71	µg/L	
200227O016	11	Room 202-SK; Initial	1.00	8.84	µg/L	
200227O017	12	Room 210-WF; Initial	1.00	6.18	µg/L	
200227O018	13	Room 210-SK; Initial	1.00	45.3	µg/L	H
200227O019	14	Girl's Bathroom by Room 210 @C-SK; Initial	1.00	12.8	µg/L	
200227O020	15	Girls Bathroom by Room 213 @B-SK; Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2201274-14240

March 16, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Jack Abrams Stem Magnet, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on March 13, 2020. New York Environmental analyzed the samples on March 16, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	13 Mar 2020
Date Received:	13 Mar 2020
Date Analyzed:	16 Mar 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
200316K001	1	Girl's Locker Room @ A-SK, Initial	1.00	3.84	µg/L	
200316K002	2	Room 210-SK, Initial	1.00	14.0	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix F

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen Prep	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1001-2	Kitchen Custodial Closet	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1001-3	Kitchen Sanitizer Station @ A	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1001-4	Kitchen Sanitizer Station	SY	App	1.17	1/10/2020	-	-	-	None	-	-	-
1001-5	Kitchen Sanitizer Station @ B	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1001-6	Kitchen Handwash	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1001-7	Kitchen Bathroom	SK	App	5.83	1/10/2020	-	-	-	None	-	-	-
1002-1	Faculty Lounge	SK	App	1.31	1/10/2020	-	-	-	None	-	-	-
1003-1	Mens Faculty Bathroom in Main Lobby @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1003-2	Mens Faculty Bathroom in Main Lobby @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1004-1	Womens Faculty Bathroom in Main Lobby @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1004-2	Womens Faculty Bathroom in Main Lobby @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1005-1	Room 2	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1006-1	Room 3	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1007-1	Room 4	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1008-1	Room 5	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1008-2	Room 5	WF	App	1.08	1/10/2020	-	-	-	None	-	-	-
1009-1	Room 6	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1010-1	Room 7	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1010-2	Room 7	WF	App	2.03	1/10/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1010-3	Room 7 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1011-1	Room 8 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1011-2	Room 8	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1011-3	Room 8	WF	App	4.1	1/10/2020	-	-	-	None	-	-	-
1012-1	Room 10	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1012-2	Room 10	WF	App	19.9	2/12/2020				None	CAPPED		
1012-3	Room 10 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1013-1	Room 11	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1013-2	Room 11	WF	App	3.55	1/10/2020	-	-	-	None	-	-	-
1013-3	Room 11 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1014-1	Room 12	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1014-2	Room 12	WF	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1015-1	Girls Bathroom by Room 12 @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1015-2	Girls Bathroom by Room 12 @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1015-3	Girls Bathroom by Room 12 @ C	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1015-4	Girls Bathroom by Room 12 in Womens Faculty	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1016-1	Hallway by Room 12	WF	App	1.15	1/10/2020	-	-	-	None	-	-	-
1017-1	Custodial Closet by Room 12	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1018-1	Boys Bathroom by Room 12 @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1018-2	Boys Bathroom by Room 12 @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1018-3	Boys Bathroom by Room 12 @ C	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1018-4	Boys Bathroom by Room 12 in Mens Faculty	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1019-1	Main Office Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1019-2	Main Office Break Room	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1020-1	Nurse's Office Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1021-1	Hallway by Room 15	WF	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1021-2	Hallway by Room 15	BF	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1022-1	Room 27 Counter @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1022-2	Room 27 Counter @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1023-1	Boys Bathroom by Room 26 @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1023-2	Boys Bathroom by Room 26 @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1023-3	Boys Bathroom by Room 26 @ C	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1023-4	Boys Bathroom by Room 26 in Mens Faculty	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1024-1	Custodial Closet by Room 26	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1025-1	Hallway by Room 26	WF	App	1.45	1/10/2020	-	-	-	None	-	-	-
1026-1	Girls Bathroom by Room 26 @ A	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1026-2	Girls Bathroom by Room 26 @ B	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1026-3	Girls Bathroom by Room 26 @ C	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1026-4	Girls Bathroom by Room 26 in Womens Faculty	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1027-1	Room 26	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1027-2	Room 26	WF	App	4.06	1/10/2020	-	-	-	None	-	-	-
1028-1	Room 25 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1028-2	Room 25	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1028-3	Room 25	WF	App	6.75	1/10/2020	-	-	-	None	-	-	-
1029-1	Room 24 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1029-2	Room 24	WF	App		1/10/2020	-	-	-	None	CAPPED	-	-
1029-3	Room 24	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1030-1	Room 22	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1030-2	Room 22	WF	App	12.9	1/10/2020	-	-	-	None	-	-	-
1030-3	Room 22 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1031-1	Room 21 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1031-2	Room 21	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1031-3	Room 21	WF	App	7.09	1/10/2020	-	-	-	None	-	-	-
1032-1	Room 20	WF	App	2.34	1/10/2020	-	-	-	None	-	-	-
1032-2	Room 20 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1032-3	Room 20	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1033-1	Room 19	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1033-2	Room 19 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1033-3	Room 19	WF	App		1/10/2020	-	-	-	None	CAPPED	-	-
1034-1	Room 18	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1034-2	Room 18 Bathroom	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1034-3	Room 18	WF	App	6.65	1/10/2020	-	-	-	None	-	-	-
1035-1	Room 17	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1035-2	Room 17	WF	App		1/10/2020	-	-	-	None	CAPPED	-	-
1035-3	Room 17 Bathroom	SK	App	1.2	1/10/2020	-	-	-	None	-	-	-
1036-1	Room 16	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1036-2	Room 16	WF	App	4.09	1/10/2020	-	-	-	None	-	-	-
1036-3	Room 16 Bathroom	SK	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1037-1	Room 15	SK	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1037-2	Room 15	WF	App	<1.0	1/10/2020	-	-	-	None	-	-	-
1037-3	Room 15 Bathroom	SK	App	2.23	1/10/2020	-	-	-	None	-	-	-
1038-1	Room 14	SK	N/A	<1.0	1/10/2020	-	-	-	None	SIGN	-	-
1038-2	Room 14 Bathroom	SK	App		1/10/2020	-	-	-	None	-	-	-
1039-1	Custodial Office	SS	N/A		1/10/2020	-	-	-	None	SIGN	-	-
1039-2	Custodial Office Bathroom	SK	App	4.05	1/10/2020	-	-	-	None	-	-	-
1040-1	Hallway by Custodial Office	WF	App	5.36	1/10/2020	-	-	-	None	-	-	-

Laboratory Report

NYE Report #: 2200175-13637

January 13, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Woodhull Intermediate, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on January 10, 2020. New York Environmental analyzed the samples on January 11, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	10 Jan 2020
Date Received:	10 Jan 2020
Date Analyzed:	11 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200110P153	1	Kitchen Prep - SK; Initial	1.00	<1.00	µg/L	
200110P154	2	Kitchen Sanitizer Station @ A - SK; Initial	1.00	<1.00	µg/L	
200110P155	3	Kitchen Sanitizer Station - SY; Initial	1.00	1.17	µg/L	
200110P156	4	Kitchen Sanitizer Station @ B - SK; Initial	1.00	<1.00	µg/L	
200110P157	5	Kitchen Handwash - SK; Initial	1.00	<1.00	µg/L	
200110P158	6	Kitchen Bathroom - SK; Initial	1.00	5.83	µg/L	
200110P159	7	Faculty Lounge - SK; Initial	1.00	1.31	µg/L	
200110P160	8	Room 5 - WF; Initial	1.00	1.08	µg/L	
200110P161	9	Room 7 - WF; Initial	1.00	2.03	µg/L	
200110P162	10	Room 8 - WF; Initial	1.00	4.10	µg/L	
200110P163	11	Room 10 - WF; Initial	1.00	20.3	µg/L	H
200110P164	12	Room 11 - WF; Initial	1.00	3.55	µg/L	
200110P165	13	Room 12 - WF; Initial	1.00	<1.00	µg/L	
200110P166	14	Hallway by Room 12 - WF; Initial	1.00	1.15	µg/L	
200110P167	15	Hallway by Room 15 - WF; Initial	1.00	<1.00	µg/L	
200110P168	16	Hallway by Room 15 - BF; Initial	1.00	<1.00	µg/L	
200110P169	17	Hallway by Room 26 - WF; Initial	1.00	1.45	µg/L	
200110P170	18	Room 26 - WF; Initial	1.00	4.06	µg/L	
200110P171	19	Room 25 - WF; Initial	1.00	6.75	µg/L	
200110P172	20	Room 22 - WF; Initial	1.00	12.9	µg/L	
200110P173	21	Room 21 - WF; Initial	1.00	7.09	µg/L	
200110P174	22	Room 20 - WF; Initial	1.00	2.34	µg/L	
200110P175	23	Room 18 - WF; Initial	1.00	6.65	µg/L	
200110P176	24	Room 17 Bathroom - SK; Initial	1.00	1.20	µg/L	
200110P177	25	Room 16 - WF; Initial	1.00	4.09	µg/L	
200110P178	26	Room 16 Bathroom - SK; Initial	1.00	<1.00	µg/L	



Date Collected:	10 Jan 2020
Date Received:	10 Jan 2020
Date Analyzed:	11 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200110P179	27	Room 15 - WF; Initial	1.00	<1.00	µg/L	
200110P180	28	Room 15 Bathroom - SK; Initial	1.00	2.23	µg/L	
200110P181	29	Room 14 Bathroom - SK; Initial	1.00	<1.00	µg/L	
200110P182	30	Custodial Office Bathroom - SK; Initial	1.00	4.05	µg/L	
200110P183	31	Hallway by Custodial Office - WF; Initial	1.00	5.36	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.

Laboratory Report

NYE Report #: 2200712-13954

February 14, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Woodhull Intermediate School, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 14, 2020. New York Environmental analyzed the samples on February 14, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	12 Feb 2020
Date Received:	14 Feb 2020
Date Analyzed:	14 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
200214K022	1	Room 10 - WF; Initial	1.00	19.9	µg/L	H

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.



Appendix G

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen Handwash @ A	SK	App	2.52	1/9/2020	-	-	-	None	-	-	-
1001-2	Kitchen West Serving Line Handwash	SK	App	2.81	1/9/2020	-	-	-	None	-	-	-
1001-3	Dishwashing Station	SPY	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1001-4	Dishwashing Station	SK	App	3.34	2/27/2020	-	-	-	None	-	-	-
1001-5	Kitchen East Serving Line Handwash	SK	App	3.44	1/9/2020	-	-	-	None	-	-	-
1001-6	Kitchen Sanitizer Station	SK	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1001-7	Kitchen Sanitizer Station	SY	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1001-8	Kitchen Handwash @ B	SK	App	3.09	1/9/2020	-	-	-	None	-	-	-
1001-9	Kitchen Pot Filler at Stove	SP	App	9.89	1/9/2020	-	-	-	None	-	-	-
1001-10	Kitchen Pot Filler at Steamer	SP	App	3.32	1/9/2020	-	-	-	None	-	-	-
1001-11	Kitchen Prep Sink @ A	SK	App	1.27	1/9/2020	-	-	-	None	-	-	-
1001-12	Kitchen Prep Sink @ B	SK	App	1.08	1/9/2020	-	-	-	None	-	-	-
1001-13	Dishwashing Station Handwash	SK	App	1.78	1/9/2020	-	-	-	None	-	-	-
1001-14	Kitchen Bathroom	SK	App	3.77	1/9/2020	-	-	-	None	-	-	-
1001-15	Kitchen	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1002-1	Custodian Bathroom	SK	App	4.07	1/9/2020	-	-	-	None	-	-	-
1003-1	Hallway by Custodian Bathroom	WF	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1003-2	Hallway by Custodian Bathroom	BF	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1004-1	Custodian Closet by Custodian Bathroom	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1005-1	Girls Locker Room Custodian Closet	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1005-2	Girls Locker Room Bathroom @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1005-3	Girls Locker Room Bathroom @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1006-1	Girls Coach's Office Bathroom	SK	App	9.1	1/9/2020	-	-	-	None	-	-	-
1007-1	Hallway by Boys Coach's Office	SK	App	1.26	1/9/2020	-	-	-	None	-	-	-
1008-1	Boys Coach's Office Bathroom	SK	App	1.83	1/9/2020	-	-	-	None	-	-	-
1009-1	Boys Locker Room Custodian Closet	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1009-2	Boys Locker Room Bathroom @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1009-3	Boys Locker Room Bathroom @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1009-4	Boys Locker Room	WF	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1010-1	Mens Bathroom by Boys Locker Room	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1011-1	Room 302 Unit @ A	SK	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1011-2	Room 302 Unit @ B	SK	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1011-3	Room 302 Unit @ C	SK	App	3.62	1/9/2020	-	-	-	None	-	-	-
1012-1	Room 301 Unit @ A	SK	App	1.25	1/9/2020	-	-	-	None	-	-	-
1012-2	Room 301 Unit @ B	SK	App	1.17	1/9/2020	-	-	-	None	-	-	-
1012-3	Room 301 Unit @ C	SK	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1013-1	Room 110 Teacher's Station	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1013-2	Room 110 Table 1	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1013-3	Room 110 Table 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1013-4	Room 110 Table 3	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1013-5	Room 110 Table 4	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1013-6	Room 110 Table 5	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1013-7	Room 110 Table 6	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1013-8	Room 110 Table 7	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1014-1	Prep Room 110 / 109 Counter 1 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1014-2	Prep Room 110 / 109 Counter 1 @ B	SK	N/A	35	1/9/2020				None	SIGN		
1014-3	Prep Room 110 / 109 Counter 2	SK	App	3.26	1/9/2020	-	-	-	None	-	-	-
1015-1	Room 109 Teacher's Station	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1015-2	Room 109 Table 1	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1015-3	Room 109 Table 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1015-4	Room 109 Table 3	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1015-5	Room 109 Table 4	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1015-6	Room 109 Table 5	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1015-7	Room 109 Table 6	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1015-8	Room 109 Table 7	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1016-1	Custodian Closet by Room 109	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1017-1	Hallway by Room 107	WF	App	1.38	1/9/2020	-	-	-	None	-	-	-
1017-2	Hallway by Room 105	WF	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1018-1	Boys Bathroom Blue Floor @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1018-2	Boys Bathroom Blue Floor @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1018-3	Boys Bathroom Blue Floor @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1018-4	Boys Bathroom Blue Floor @ D	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1019-1	Lobby Blue Floor	WF	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1019-2	Lobby Blue Floor	BF	App	<1.0	1/9/2020	-	-	-	None	-	-	-
1020-1	Girls Bathroom Blue Floor @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1020-2	Girls Bathroom Blue Floor @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1021-1	Principal's Office Bathroom	SK	App	11.8	1/9/2020	-	-	-	None	-	-	-
1021-2	Main Office Break Room Bathroom	SK	App	2.55	1/9/2020	-	-	-	None	-	-	-
1022-1	Nurse's Office Break Area	SK	App	2.6	1/9/2020	-	-	-	None	-	-	-
1022-2	Nurse's Office	SK	App	1.82	1/9/2020	-	-	-	None	-	-	-
1022-3	Nurse's Office Bathroom	SK	App	2.2	1/9/2020	-	-	-	None	-	-	-
1023-1	Women Faculty Bathroom by ISS Room	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1024-1	Hallway by Room 123	WF	App	1.01	1/9/2020	-	-	-	None	-	-	-
1025-1	Men Faculty Bathroom by Room 123	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1026-1	Boys Bathroom by Room 123 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1026-2	Boys Bathroom by Room 123 @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1026-3	Boys Bathroom by Room 123 @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1027-1	Girls Bathroom by Room 123 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1027-2	Girls Bathroom by Room 123 @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1027-3	Girls Bathroom by Room 123 @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1028-1	Custodian Closet by Room 116	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1029-1	Room 116 Teacher's Station	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1029-2	Room 116 Table 1	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1029-3	Room 116 Table 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1029-4	Room 116 Table 3	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1029-5	Room 116 Table 4	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1029-6	Room 116 Table 5	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1029-7	Room 116 Table 6	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1029-8	Room 116 Table 7	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1030-1	Prep Room 116 Counter 1 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1030-2	Prep Room 116 Counter 1 @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1030-3	Prep Room 116 Counter 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1031-1	Hallway by Room 115	WF	App	1.34	1/9/2020	-	-	-	None	-	-	-
1032-1	Mens Bathroom by Faculty Room	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1033-1	Womens Bathroom by Faculty Room	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
1034-1	Audio Visual Room	SK	App	3.15	1/9/2020	-	-	-	None	-	-	-
1035-1	Hallway by Room 112	WF	App	1.54	1/9/2020	-	-	-	None	-	-	-
2001-1	Room 223 Unit @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2001-2	Room 223 Unit @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2001-3	Room 223 Unit @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2001-4	Room 223 Unit @ D	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2001-5	Room 223 Unit @ E	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2001-6	Room 223 Unit @ F	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2002-1	Room 222 Unit @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2002-2	Room 222 Unit @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2002-3	Room 222 Unit @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2002-4	Room 222 Unit @ D	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2002-5	Room 222 Unit @ E	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2002-6	Room 222 Unit @ F	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2003-1	Hallway by Room 221	WF	App		1/9/2020	-	-	-	None	CAPPED	-	-
2004-1	Room 221 Counter @ A	SK	App	7.32	1/9/2020	-	-	-	None	-	-	-
2004-2	Room 221 Counter @ B	SK	App	2.33	1/9/2020	-	-	-	None	-	-	-
2005-1	Hallway by Room 218	WF	App	<1.0	1/9/2020	-	-	-	None	-	-	-
2006-1	Boys Bathroom by Room 218 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2006-2	Boys Bathroom by Room 218 @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2006-3	Boys Bathroom by Room 218 @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2007-1	Mens Faculty Bathroom inside Boys Bathroom	SK	App	9.84	1/9/2020	-	-	-	None	-	-	-
2008-1	Girls Bathroom by Room 211 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2008-2	Girls Bathroom by Room 211 @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2009-1	Womens Faculty Bathroom inside Girls Bathroom	SK	App	2.69	1/9/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2010-1	Custodian Closet by Room 211	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2011-1	Room 211 Teacher's Station	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2011-2	Room 211 Table 1	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2011-3	Room 211 Table 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2011-4	Room 211 Table 3	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2011-5	Room 211 Table 4	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2011-6	Room 211 Table 5	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2011-7	Room 211 Table 6	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2011-8	Room 211 Table 7	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2012-1	Prep Room 211 / 210 Counter 1 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2012-2	Prep Room 211 / 210 Counter 1 @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2012-3	Prep Room 211 / 210 Counter 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2013-1	Hallway by Room 210	WF	App	1.54	1/9/2020	-	-	-	None	-	-	-
2014-1	Room 210 Teacher's Station	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2014-2	Room 210 Table 1	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2014-3	Room 210 Table 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2014-4	Room 210 Table 3	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2014-5	Room 210 Table 4	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2014-6	Room 210 Table 5	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2014-7	Room 210 Table 6	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2014-8	Room 210 Table 7	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2015-1	Library Office	SK	App	<1.0	1/9/2020	-	-	-	None	-	-	-
2016-1	Room 208 Station 1	SK	App	4.84	2/12/2020	-	-	-	None	-	-	-
2016-2	Room 208 Station 2	SK	App	3.81	2/12/2020	-	-	-	None	-	-	-
2016-3	Room 208 Station 3	SK	App	11.1	1/9/2020	-	-	-	None	-	-	-
2016-4	Room 208 Station 4	SK	App	11	1/9/2020	-	-	-	None	-	-	-
2017-1	Hallway by Room 207	WF	App	2.13	1/9/2020	-	-	-	None	-	-	-
2018-1	Room 207 Station 1	SK	App	2.69	1/9/2020	-	-	-	None	-	-	-
2018-2	Room 207 Station 2	SK	App	2.62	1/9/2020	-	-	-	None	-	-	-
2018-3	Room 207 Station 3	SK	App	5.22	2/12/2020	-	-	-	None	-	-	-
2018-4	Room 207 Station 4	SK	App	5.49	1/9/2020	-	-	-	None	-	-	-
2019-1	Room 205 Teacher's Station	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2019-2	Room 205 Table 1	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2020-1	Prep Room 205 / 204 Conter @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2020-2	Prep Room 205 / 204 Conter @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2020-3	Prep Room 205 / 204 Conter @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2021-1	Room 204 Teacher's Station	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2021-2	Room 204 Table 1	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2021-3	Room 204 Table 2	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2021-4	Room 204 Table 3	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2021-5	Room 204 Table 4	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2021-6	Room 204 Table 5	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2021-7	Room 204 Table 6	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2021-8	Room 204 Table 7	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2022-1	Custodian Closet by Room 204	SS	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2023-1	Girls Bathroom by Room 203 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2023-2	Girls Bathroom by Room 203 @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2023-3	Girls Bathroom by Room 203 @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2024-1	Women Faculty Bathroom inside Girls Bathroom	SK	App	4.68	1/9/2020	-	-	-	None	-	-	-
2025-1	Hallway by Room 203	WF	App	1.6	1/9/2020	-	-	-	None	-	-	-
2026-1	Boys Bathroom by Room 201 @ A	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2026-2	Boys Bathroom by Room 201 @ B	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2026-3	Boys Bathroom by Room 201 @ C	SK	N/A		1/9/2020	-	-	-	None	SIGN	-	-
2027-1	Men Faculty Bathroom inside Boys Bathroom	SK	App	9.05	1/9/2020	-	-	-	None	-	-	-

Laboratory Report

NYE Report #: 2200145-13610

January 13, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: J. Taylor Finley Middle School, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on January 09, 2020. New York Environmental analyzed the samples on January 10, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	09 Jan 2020
Date Received:	09 Jan 2020
Date Analyzed:	10 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200109O089	1	Kitchen Handwash @ A - SK; Initial	1.00	2.52	µg/L	
200109O090	2	Kitchen West Serving Line Handwash - SK; Initial	1.00	2.81	µg/L	
200109O091	3	Dishwashing Station - SY; Initial	1.00	<1.00	µg/L	
200109O092	4	Dishwashing Station - SK; Initial	1.00	30.0	µg/L	H
200109O093	5	Kitchen East Serving Line Handwash - SK; Initial	1.00	3.44	µg/L	
200109O094	6	Kitchen Sanitizer Station - SK; Initial	1.00	<1.00	µg/L	
200109O095	7	Kitchen Sanitizer Station - SY; Initial	1.00	<1.00	µg/L	
200109O096	8	Kitchen Handwash @ B - SK; Initial	1.00	3.09	µg/L	
200109O097	9	Kitchen Pot Filler at Stove - SP; Initial	1.00	9.86	µg/L	
200109O098	10	Kitchen Pot Filler at Steamer - SP; Initial	1.00	3.32	µg/L	
200109O099	11	Kitchen Prep Sink @ A - SK; Initial	1.00	1.27	µg/L	
200109O100	12	Kitchen Prep Sink @ B - SK; Initial	1.00	1.08	µg/L	
200109O101	13	Dishwashing Station Handwash - SK; Initial	1.00	1.78	µg/L	
200109O102	14	Kitchen Bathroom - SK; Initial	1.00	3.77	µg/L	
200109O103	15	Custodian Bathroom - SK; Initial	1.00	4.07	µg/L	
200109O104	16	Hallway by Custodian Bathroom - WF; Initial	1.00	<1.00	µg/L	
200109O105	17	Hallway by Custodian Bathroom - BF; Initial	1.00	<1.00	µg/L	
200109O106	18	Girls Coach's Office Bathroom - SK; Initial	1.00	9.10	µg/L	
200109O107	19	Hallway by Boys Coach's Office - SK; Initial	1.00	1.26	µg/L	
200109O108	20	Boys Coach's Office Bathroom - SK; Initial	1.00	1.83	µg/L	
200109O109	21	Boys Locker Room - WF; Initial	1.00	<1.00	µg/L	
200109O110	22	Room 302 Unit @ A - SK; Initial	1.00	<1.00	µg/L	
200109O111	23	Room 302 Unit @ B - SK; Initial	1.00	<1.00	µg/L	
200109O112	24	Room 302 Unit @ C - SK; Initial	1.00	3.62	µg/L	
200109O113	25	Room 301 Unit @ A - SK; Initial	1.00	1.25	µg/L	
200109O114	26	Room 301 Unit @ B - SK; Initial	1.00	1.17	µg/L	



Date Collected:	09 Jan 2020
Date Received:	09 Jan 2020
Date Analyzed:	10 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200109O115	27	Room 301 Unit @ C - SK; Initial	1.00	<1.00	µg/L	
200109O116	28	Prep Room 110 / 109 Counter 1 @ B - SK; Initial	1.00	35.0	µg/L	H
200109O117	29	Prep Room 110 / 109 Counter 2 - SK; Initial	1.00	3.26	µg/L	
200109O118	30	Hallway by Room 107 - WF; Initial	1.00	1.38	µg/L	
200109O119	31	Hallway by Room 105 - WF; Initial	1.00	<1.00	µg/L	
200109O120	32	Lobby Blue Floor - WF; Initial	1.00	<1.00	µg/L	
200109O121	33	Lobby Blue Floor - BF; Initial	1.00	<1.00	µg/L	
200109O122	34	Principal's Office Bathroom - SK; Initial	1.00	11.8	µg/L	
200109O123	35	Main Office Break Room Bathroom - SK; Initial	1.00	2.55	µg/L	
200109O124	36	Nurse's Office Break Area - SK; Initial	1.00	2.60	µg/L	
200109O125	37	Nurse's Office - SK; Initial	1.00	1.82	µg/L	
200109O126	38	Nurse's Office Bathroom - SK; Initial	1.00	2.20	µg/L	
200109O127	39	Hallway by Room 123 - WF; Initial	1.00	1.01	µg/L	
200109O128	40	Hallway by Room 115 - WF; Initial	1.00	1.34	µg/L	
200109O129	41	Audio Visual Room - SK; Initial	1.00	3.15	µg/L	
200109O130	42	Hallway by Room 112 - WF; Initial	1.00	1.54	µg/L	
200109O131	43	Room 221 Counter @ A - SK; Initial	1.00	7.32	µg/L	
200109O132	44	Room 221 Counter @ B - SK; Initial	1.00	2.33	µg/L	
200109O133	45	Hallway by Room 218 - WF; Initial	1.00	<1.00	µg/L	
200109O134	46	Mens Faculty Bathroom inside Boys Bathroom - SK; Initial	1.00	9.84	µg/L	
200109O135	47	Womens Faculty Bathroom inside Girls Bathroom - SK; Initial	1.00	2.69	µg/L	
200109O136	48	Hallway by Room 210 - WF; Initial	1.00	1.54	µg/L	
200109O137	49	Library Office - SK; Initial	1.00	<1.00	µg/L	
200109O138	50	Room 208 Station 1 - SK; Initial	1.00	66.6	µg/L	E,H
200109O139	51	Room 208 Station 2 - SK; Initial	1.00	107	µg/L	E,H
200109O140	52	Room 208 Station 3 - SK; Initial	1.00	11.1	µg/L	
200109O141	53	Room 208 Station 4 - SK; Initial	1.00	11.0	µg/L	



Date Collected:	09 Jan 2020
Date Received:	09 Jan 2020
Date Analyzed:	10 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200109O142	54	Hallway by Room 207 - WF; Initial	1.00	2.13	µg/L	
200109O143	55	Room 207 Station 1 - SK; Initial	1.00	2.69	µg/L	
200109O144	56	Room 207 Station 2 - SK; Initial	1.00	2.62	µg/L	
200109O145	57	Room 207 Station 3 - SK; Initial	1.00	17.0	µg/L	H
200109O146	58	Room 207 Station 4 - SK; Initial	1.00	5.49	µg/L	
200109O147	59	Women Faculty Bathroom inside Girls Bathroom - SK; Initial	1.00	4.68	µg/L	
200109O148	60	Hallway by Room 203 - WF; Initial	1.00	1.60	µg/L	
200109O149	61	Men Faculty Bathroom inside Boys Bathroom - SK; Initial	1.00	9.05	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2200713-13955

February 14, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: J. Taylor Finley Middle School, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 14, 2020. New York Environmental analyzed the samples on February 14, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	12 Feb 2020
Date Received:	14 Feb 2020
Date Analyzed:	14 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
200214K023	1	Dishwashing Station - SK; Initial	1.00	33.8	µg/L	H
200214K024	2	Room 208 Station 1 - SK; Initial	1.00	4.84	µg/L	
200214K025	3	Room 208 Station 2 - SK; Initial	1.00	3.81	µg/L	
200214K026	4	Room 207 Station 3 - SK; Initial	1.00	5.22	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2200947-14084

March 2, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: J Taylor Finley Intermediate School Huntington, NY

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 27, 2020. New York Environmental analyzed the samples on February 28, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	27 Feb 2020
Date Received:	27 Feb 2020
Date Analyzed:	28 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
200227O001	1	Dishwashing Station-SK; Initial	1.00	3.34	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation



Appendix H

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
0001-1	Custodial Bathroom	SK	App	3.19	1/22/2020	-	-	-	None	-	-	-
0002-1	Faculty Bathroom	SK	App	3.3	1/22/2020	-	-	-	None	-	-	-
0003-1	Faculty Men's Bathroom @A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0003-2	Faculty Men's Bathroom @B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0003-3	Faculty Men's Bathroom @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0004-1	Faculty Women's Bathroom @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0004-2	Faculty Women's Bathroom @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0004-3	Faculty Women's Bathroom @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0004-4	Faculty Women's Bathroom @ D	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0005-1	Hallway by Building & Grounds Office	WF	App	<1.0	1/22/2020	-	-	-	None	-	-	-
0005-2	Hallway by Building & Grounds Office	BF	App	<1.0	1/22/2020	-	-	-	None	-	-	-
0006-1	Art Room 005 @A (Left)	SK	App	3.94	1/22/2020	-	-	-	None	-	-	-
0006-2	Art Room 005 @B (Right)	SK	App	2.98	1/22/2020	-	-	-	None	-	-	-
0007-1	Hallway by Custodial Entrance	WF	App	2.64	1/22/2020	-	-	-	None	-	-	-
0008-1	Room 011 @ A (Left)	SK	App	13.5	1/22/2020	-	-	-	None	-	-	-
0008-2	Room 011 @ B (Center)	SK	App	7.34	1/22/2020	-	-	-	None	-	-	-
0008-3	Room 011 @ C (Right)	SK	App	9.79	1/22/2020	-	-	-	None	-	-	-
0009-1	Room 012 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0009-2	Room 012 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0009-3	Room 012 @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
0009-4	Room 012 Photo Lab	SK	App	<1.0	1/22/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
0010-1	Robotics Room	SK	App	1.35	1/22/2020	-	-	-	None	-	-	-
1001-1	Kitchen Handwash A	SK	App	2.21	1/22/2020	-	-	-	None	-	-	-
1001-2	Kitchen Prep @A	SK	App	<1.0	2/12/2020	-	-	-	None	-	-	-
1001-3	Kitchen Prep @B	SK	App	<1.0	2/12/2020	-	-	-	None	-	-	-
1001-4	Kitchen Handwash B	SK	App	5.81	1/22/2020	-	-	-	None	-	-	-
1001-5	Kitchen Dishwasher Station	SPY	App	5.29	1/22/2020	-	-	-	None	-	-	-
1001-6	Kitchen Sanitizer Station @A	SK	App	<1.0	1/22/2020	-	-	-	None	-	-	-
1001-7	Kitchen Sanitizer Station @B	SK	App	1.5	1/22/2020	-	-	-	None	-	-	-
1001-8	Kitchen Sanitizer Station @C	SK	App	3.16	1/22/2020	-	-	-	None	-	-	-
1001-9	Kitchen Island	SK	App	7.46	1/22/2020	-	-	-	None	-	-	-
1001-10	Kitchen Pot Filler by Stove	PF	App	62.8	1/22/2020				None	CAPPED		
1001-11	Kitchen Pot Filler Spray by Oven	SPY	App	20.7	1/22/2020				None	CAPPED		
1001-12	North Serving Line	SK	App	7.69	1/22/2020	-	-	-	None	-	-	-
1001-13	South Serving Line	SK	App	7.67	1/22/2020	-	-	-	None	-	-	-
1001-14	South Serving Line Handwash	SK	App	<1.0	1/22/2020	-	-	-	None	-	-	-
1002-1	Cafeteria B	WF	App	<1.0	1/22/2020	-	-	-	None	-	-	-
1002-2	Cafeteria B	BF	App	<1.0	1/22/2020	-	-	-	None	-	-	-
1003-1	Room 105 Unit @ A	SK	App	6.71	1/22/2020	-	-	-	None	-	-	-
1003-2	Room 105 Unit @ B	SK	App	1.99	1/22/2020	-	-	-	None	-	-	-
1003-3	Room 105 Unit @ C	SK	App	11.8	1/22/2020	-	-	-	None	-	-	-
1004-1	Hallway by Room 105	WF	App	3.25	1/22/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1005-1	Men's Bathroom by Room 105 Unit @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1005-2	Men's Bathroom by Room 105 Unit @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1005-3	Men's Bathroom by Room 105 Unit @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1005-4	Men's Bathroom by Room 105 Unit @ D	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1006-1	Custodial Closet by Room 105	SS	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1007-1	Women's Bathroom by Room 105 Unit @A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1007-2	Women's Bathroom by Room 105 Unit @B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1007-3	Women's Bathroom by Room 105 Unit @C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1007-4	Women's Bathroom by Room 105 Unit @D	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1008-1	Room 106 Unit @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1008-2	Room 106 Unit @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1008-3	Room 106 Unit @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1009-1	Room 107 Unit @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1009-2	Room 107 Unit @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1010-1	Hallway by Room 107	WF	App	<1.0	1/22/2020	-	-	-	None	-	-	-
1011-1	Room 108	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1012-1	Men's Faculty Bathroom by Room 108 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1012-2	Men's Faculty Bathroom by Room 108 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1013-1	Women's Faculty Bathroom by Room 108 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1013-2	Women's Faculty Bathroom by Room 108 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1014-1	Hallway by Room 103	WF	App	1.29	1/22/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1015-1	Hallway by Room 101	WF	App	5.31	1/22/2020	-	-	-	None	-	-	-
1016-1	Room 161	SK	App	4.48	2/12/2020	-	-	-	None	-	-	-
1017-1	Main Office Bathroom	SK	App	2.37	1/22/2020	-	-	-	None	-	-	-
1018-1	Nurse's Office	SK	App	4.47	1/22/2020	-	-	-	None	-	-	-
1018-2	Nurse's Office Bathroom	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1018-3	Nurse's Waiting Room	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1019-1	Hallway by Room 109	WF	App	<1.0	1/22/2020	-	-	-	None	-	-	-
1020-1	Room 109 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1020-2	Room 109 Counter 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1020-3	Room 109 Counter 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1020-4	Room 109 Counter 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1020-5	Room 109 Counter 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1021-1	Hallway by Room 110	WF	App	3.26	1/22/2020	-	-	-	None	-	-	-
1022-1	Room 110 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1022-2	Room 110 Counter @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1022-3	Room 110 Counter @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1022-4	Room 110 Counter @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1022-5	Room 110 Table 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1022-6	Room 110 Table 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1022-7	Room 110 Table 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1022-8	Room 110 Table 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1022-9	Room 110 Table 3 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1022-10	Room 110 Table 3 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1023-1	Room 110 Prep	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1024-1	Prep Room Across from Room 110	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1025-1	Custodial Closet by Room 114	SS	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1026-1	Room 114 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1026-2	Room 114 Counter 1	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1026-3	Room 114 Counter 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1026-4	Room 114 Counter 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1027-1	Room 113 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1027-2	Room 113 Counter 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1027-3	Room 113 Counter 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1027-4	Room 113 Counter 2	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-1	Room 112 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-2	Room 112 Counter @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-3	Room 112 Counter @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-4	Room 112 Counter @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-5	Room 112 Table 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-6	Room 112 Table 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-7	Room 112 Table 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-8	Room 112 Table 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1028-9	Room 112 Table 3 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1028-10	Room 112 Table 3 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1029-1	Hallway by Room 112	WF	App	10.3	1/22/2020	-	-	-	None	-	-	-
1030-1	Faculty Dining Room	SK	App	1.08	1/22/2020	-	-	-	None	-	-	-
1031-1	Hallway by Cafeteria B	WF	App	4.52	1/22/2020	-	-	-	None	-	-	-
1032-1	Hallway Ramp (East)	WF	App	3.23	1/22/2020	-	-	-	None	-	-	-
1033-1	Women's Bathroom by Room 143	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1034-1	Custodial Closet by Room 143	SS	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-1	Room 143 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-2	Room 143 Counter @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-3	Room 143 Counter @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-4	Room 143 Counter @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-5	Room 143 Table 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-6	Room 143 Table 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-7	Room 143 Table 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-8	Room 143 Table 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-9	Room 143 Table 3 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1035-10	Room 143 Table 3 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1036-1	Prep Room 143/141 Counter @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1036-2	Prep Room 143/141 Counter @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-1	Room 141 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1037-2	Room 141 Counter @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-3	Room 141 Counter @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-4	Room 141 Counter @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-5	Room 141 Table 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-6	Room 141 Table 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-7	Room 141 Table 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-8	Room 141 Table 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-9	Room 141 Table 3 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1037-10	Room 141 Table 3 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-1	Room 144 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-2	Room 144 Fume Hood	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-3	Room 144 Counter	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-4	Room 144 Pod 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-5	Room 144 Pod 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-6	Room 144 Pod 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-7	Room 144 Pod 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-8	Room 144 Pod 3 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-9	Room 144 Pod 3 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-10	Room 144 Pod 4 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-11	Room 144 Pod 4 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-12	Room 144 Pod 5 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1038-13	Room 144 Pod 5 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-14	Room 144 Pod 6 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1038-15	Room 144 Pod 6 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1039-1	Prep Room 144 / 145	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-1	Room 145 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-2	Room 145 Counter	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-3	Room 145 Fume Hood	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-4	Room 145 Pod 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-5	Room 145 Pod 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-6	Room 145 Pod 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-7	Room 145 Pod 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-8	Room 145 Pod 3 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-9	Room 145 Pod 3 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-10	Room 145 Pod 4 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-11	Room 145 Pod 4 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-12	Room 145 Pod 5 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-13	Room 145 Pod 5 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-14	Room 145 Pod 6 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1040-15	Room 145 Pod 6 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1041-1	Hallway by Room 145	WF	App		1/22/2020	-	-	-	None	CAPPED	-	-
1042-1	Room 146 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1042-2	Room 146 Counter	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-3	Room 146 Table 1 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-4	Room 146 Table 1 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-5	Room 146 Table 2 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-6	Room 146 Table 2 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-7	Room 146 Table 3 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-8	Room 146 Table 3 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-9	Room 146 Table 4	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-10	Room 146 Table 5 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-11	Room 146 Table 5 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-12	Room 146 Table 6 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-13	Room 146 Table 6 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-14	Room 146 Table 7 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1042-15	Room 146 Table 7 @ B	SK	N/A		1/22/2020	-	-	-	None	CAPPED	-	-
1043-1	Prep Room 146 Counter 1	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1043-2	Prep Room 146 Counter 2	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1044-1	Hallway by Room 150	WF	App	14.9	1/22/2020	-	-	-	None	-	-	-
1045-1	Room 148 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1045-2	Room 148 Eye Wash Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1046-1	Room 150 Teacher's Station	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1046-2	Room 150 Counter 1	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1046-3	Room 150 Counter 2	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1047-1	Hallway by Room 141	WF	App		1/22/2020	-	-	-	None	CAPPED	-	-
1048-1	Men's Faculty Bathroom Across from Elevator @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1048-2	Men's Faculty Bathroom Across from Elevator @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1048-3	Men's Faculty Bathroom Across from Elevator @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1048-4	Men's Faculty Bathroom Across from Elevator @ D	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1049-1	Hallway by Room 132 (Security Office)	WF	App	13	1/22/2020	-	-	-	None	-	-	-
1050-1	Men's Bathroom by Room 123 Unit @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1050-2	Men's Bathroom by Room 123 Unit @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1050-3	Men's Bathroom by Room 123 Unit @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1050-4	Men's Bathroom by Room 123 Unit @ D	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1051-1	Custodial Closet by Room 123	SS	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1052-1	Women's Bathroom by Room 123 Unit @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1052-2	Women's Bathroom by Room 123 Unit @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1052-3	Women's Bathroom by Room 123 Unit @ C	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1052-4	Women's Bathroom by Room 123 Unit @ D	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1053-1	Hallway by Room 123	WF	App	1.41	1/22/2020	-	-	-	None	-	-	-
1054-1	Library Office (Room 110)	SK	App	1.39	2/12/2020	-	-	-	None	-	-	-
1055-1	Hallway by Library Office	WF	App	2.62	1/22/2020	-	-	-	None	-	-	-
1056-1	Women's Bathroom by Room 122 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1056-2	Women's Bathroom by Room 122 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1057-1	Men's Bathroom by Room 122 @ A	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1057-2	Men's Bathroom by Room 122 @ B	SK	N/A		1/22/2020	-	-	-	None	SIGN	-	-
1058-1	Custodial Closet in Girl's Locker Room	SS	N/A		1/23/2020	-	-	-	None	SIGN	-	-
1058-2	Girl's Locker Room @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
1058-3	Girl's Locker Room @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
1059-1	Girl's Coach's Office Bathroom	SK	App	3.76	1/23/2020	-	-	-	None	-	-	-
1059-2	Girl's Coach's Office	WF	App	10.5	1/23/2020	-	-	-	None	-	-	-
1060-1	Gym Lobby	WF	App	<1.0	1/23/2020	-	-	-	None	-	-	-
1060-2	Gym Lobby	BF	App	<1.0	1/23/2020	-	-	-	None	-	-	-
1061-1	Boy's Coach's Office Bathroom	SK	App	8.57	1/23/2020	-	-	-	None	-	-	-
1062-1	Girl's Sports Locker Room Bathroom	WF	App	6.45	1/23/2020	-	-	-	None	-	-	-
1063-1	Custodial Closet in Girl's Sports Locker Room	SS	N/A		1/23/2020	-	-	-	None	SIGN	-	-
1063-2	Girl's Sports Locker Room Bathroom	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
1064-1	Trainer's Vestibule	WF	App	2.92	2/12/2020	-	-	-	None	-	-	-
1065-1	Trainer's Office	SK	App	6.48	1/23/2020	-	-	-	None	-	-	-
1066-1	Boy's Lower Locker Room Bathroom @A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
1066-2	Boy's Lower Locker Room Bathroom @B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2001-1	Men's Faculty Bathroom by 232A @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2001-2	Men's Faculty Bathroom by 232A @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2002-1	Teacher's Faculty Lounge	SK	App	1.09	1/23/2020	-	-	-	None	-	-	-
2003-1	Hallway by Teacher's Faculty Lounge	WF	App	<1.0	1/23/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2004-1	Women's Faculty Bathroom 261B @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2004-2	Women's Faculty Bathroom 261B @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2005-1	Hallway by Room 219	WF	App	<1.0	1/23/2020	-	-	-	None	-	-	-
2006-1	Custodial Closet by Room 219	SS	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2007-1	Hallway by Room 228	WF	App	4.99	1/23/2020	-	-	-	None	-	-	-
2008-1	Men's Faculty Bathroom-2nd Floor @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2008-2	Men's Faculty Bathroom-2nd Floor @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2008-3	Men's Faculty Bathroom-2nd Floor @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2008-4	Men's Faculty Bathroom-2nd Floor @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2009-1	Hallway by Room 241	WF	App		1/23/2020	-	-	-	None	CAPPED	-	-
2010-1	Hallway by Room 251	WF	App	11.8	1/23/2020	-	-	-	None	-	-	-
2011-1	Custodial Closet by Room 244	SS	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2012-1	Women's Faculty Bathroom by Room 244	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2013-1	Hallway Ramp-2nd Floor	WF	App	<1.0	1/23/2020	-	-	-	None	-	-	-
2014-1	Women's Faculty BR by 2nd Floor Ramp @ A	SK	N/A		1/23/2020	-	-	-	None	-	-	-
2014-2	Women's Faculty BR by 2nd Floor Ramp @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2014-3	Women's Faculty BR by 2nd Floor Ramp @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2014-4	Women's Faculty BR by 2nd Floor Ramp @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2015-1	Hallway by Room 208	WF	App	2.8	1/23/2020	-	-	-	None	-	-	-
2016-1	Room 208 Teacher's Station	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-2	Room 208 Counter @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2016-3	Room 208 Counter @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-4	Room 208 Counter @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-5	Room 208 Table 1 @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-6	Room 208 Table 1 @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-7	Room 208 Table 1 @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-8	Room 208 Table 1 @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-9	Room 208 Table 2 @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-10	Room 208 Table 2 @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-11	Room 208 Table 2 Fume Hood	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-12	Room 208 Table 2 @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-13	Room 208 Table 2 @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-14	Room 208 Table 3 @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-15	Room 208 Table 3 @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-16	Room 208 Table 3 @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2016-17	Room 208 Table 3 @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2017-1	Prep Room 208/209	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-1	Room 209 Teacher's Station	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-2	Room 209 Counter @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-3	Room 209 Counter @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-4	Room 209 Counter @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-5	Room 209 Table 1 @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2018-6	Room 209 Table 1 @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-7	Room 209 Table 1 @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-8	Room 209 Table 1 @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-9	Room 209 Table 2 @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-10	Room 209 Table 2 @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-11	Room 209 Fume Hood	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-12	Room 209 Table 2 @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-13	Room 209 Table 2 @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-14	Room 209 Table 3 @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-15	Room 209 Table 3 @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-16	Room 209 Table 3 @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2018-17	Room 209 Table 3 @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2019-1	Men's Bathroom by Room 209 @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2019-2	Men's Bathroom by Room 209 @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2019-3	Men's Bathroom by Room 209 @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2019-4	Men's Bathroom by Room 209 @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2020-1	Custodial Closet by Room 209	SS	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2021-1	Hallway by Room 203	SK	App	2.46	1/23/2020	-	-	-	None	-	-	-
2022-1	Women's Bathroom by Room 203 @ A	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2022-2	Women's Bathroom by Room 203 @ B	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2022-3	Women's Bathroom by Room 203 @ C	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1 st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2022-4	Women's Bathroom by Room 203 @ D	SK	N/A		1/23/2020	-	-	-	None	SIGN	-	-
2023-1	Hallway by Room 202	WF	App	<1.0	1/23/2020	-	-	-	None	-	-	-
2023-2	Hallway by Room 202	BF	App	<1.0	1/23/2020	-	-	-	None	-	-	-
2024-1	Room 216A	SK	App	14.9	1/23/2020	-	-	-	None	-	-	-

Laboratory Report

NYE Report #: 2200357-13736

January 27, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Huntington High School, Huntington, NY

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on January 23, 2020. New York Environmental analyzed the samples on January 24, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	22 Jan 2020
Date Received:	23 Jan 2020
Date Analyzed:	24 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200123Q001	1	Custodial Bathroom - SK; Initial	1.00	3.19	µg/L	
200123Q002	2	Faculty Bathroom - SK; Initial	1.00	3.30	µg/L	
200123Q003	3	Hallway by Building & Grounds Office - WF; Initial	1.00	<1.00	µg/L	
200123Q004	4	Hallway by Building & Grounds Office - BF; Initial	1.00	<1.00	µg/L	
200123Q005	5	Art Room 005 @A (Left) - SK; Initial	1.00	3.94	µg/L	
200123Q006	6	Art Room 005 @B (Right) - SK; Initial	1.00	2.98	µg/L	
200123Q007	7	Hallway by Custodial Entrance - WF; Initial	1.00	2.64	µg/L	
200123Q008	8	Room 011 @ A (Left) - SK; Initial	1.00	13.5	µg/L	
200123Q009	9	Room 011 @ B (Center) - SK; Initial	1.00	7.34	µg/L	
200123Q010	10	Room 011 @ C (Right) - SK; Initial	1.00	9.79	µg/L	
200123Q011	11	Room 012 Photo Lab - SK; Initial	1.00	<1.00	µg/L	
200123Q012	12	Robotics Room - SK; Initial	1.00	1.35	µg/L	
200123Q013	13	Kitchen Handwash A - SK; Initial	1.00	2.21	µg/L	
200123Q014	14	Kitchen Prep @A - SK; Initial	1.00	22.4	µg/L	H
200123Q015	15	Kitchen Prep @B - SK; Initial	1.00	27.3	µg/L	H
200123Q016	16	Kitchen Handwash B - SK; Initial	1.00	5.81	µg/L	
200123Q017	17	Kitchen Dishwasher Station - SPY; Initial	1.00	5.29	µg/L	
200123Q018	18	Kitchen Sanitizer Station @A - SK; Initial	1.00	<1.00	µg/L	
200123Q019	19	Kitchen Sanitizer Station @B - SK; Initial	1.00	1.50	µg/L	
200123Q020	20	Kitchen Sanitizer Station @C - SK; Initial	1.00	3.16	µg/L	
200123Q021	21	Kitchen Island - SK; Initial	1.00	7.46	µg/L	
200123Q022	22	Kitchen Pot Filler by Stove - PF; Initial	1.00	62.8	µg/L	E,H
200123Q023	23	Kitchen Pot Filler Spray by Oven - SPY; Initial	1.00	20.7	µg/L	H
200123Q024	24	North Serving Line - SK; Initial	1.00	7.69	µg/L	
200123Q025	25	South Serving Line - SK; Initial	1.00	7.67	µg/L	
200123Q026	26	South Serving Line Handwash - SK; Initial	1.00	<1.00	µg/L	



Date Collected:	22 Jan 2020
Date Received:	23 Jan 2020
Date Analyzed:	24 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200123Q027	27	Cafeteria B - WF; Initial	1.00	<1.00	µg/L	
200123Q028	28	Cafeteria B - BF; Initial	1.00	<1.00	µg/L	
200123Q029	29	Room 105 Unit @ A - SK; Initial	1.00	6.71	µg/L	
200123Q030	30	Room 105 Unit @ B - SK; Initial	1.00	1.99	µg/L	
200123Q031	31	Room 105 Unit @ C - SK; Initial	1.00	11.8	µg/L	
200123Q032	32	Hallway by Room 105 - WF; Initial	1.00	3.25	µg/L	
200123Q033	33	Hallway by Room 107 - WF; Initial	1.00	<1.00	µg/L	
200123Q034	34	Hallway by Room 103 - WF; Initial	1.00	1.29	µg/L	
200123Q035	35	Hallway by Room 101 - WF; Initial	1.00	5.31	µg/L	
200123Q036	36	Room 161 - SK; Initial	1.00	15.1	µg/L	H
200123Q037	37	Main Office Bathroom - SK; Initial	1.00	2.37	µg/L	
200123Q038	38	Nurse's Office - SK; Initial	1.00	4.47	µg/L	
200123Q039	39	Hallway by Room 109 - WF; Initial	1.00	<1.00	µg/L	
200123Q040	40	Hallway by Room 110 - WF; Initial	1.00	3.26	µg/L	
200123Q041	41	Hallway by Room 112 - WF; Initial	1.00	10.3	µg/L	
200123Q042	42	Faculty Dining Room - SK; Initial	1.00	1.08	µg/L	
200123Q043	43	Hallway by Cafeteria B - WF; Initial	1.00	4.52	µg/L	
200123Q044	44	Hallway Ramp (East) - WF; Initial	1.00	3.23	µg/L	
200123Q045	45	Hallway by Room 150 - WF; Initial	1.00	14.9	µg/L	
200123Q046	46	Hallway by Room 132 (Security Office) - WF; Initial	1.00	13.0	µg/L	
200123Q047	47	Hallway by Room 123 - WF; Initial	1.00	1.41	µg/L	
200123Q048	48	Library Office (Room 110) - SK; Initial	1.00	178	µg/L	E,H
200123Q049	49	Hallway by Library Office - WF; Initial	1.00	2.62	µg/L	
200123Q050	50	Girl's Coach's Office Bathroom - SK; Initial	1.00	3.76	µg/L	
200123Q051	51	Girl's Coach's Office - WF; Initial	1.00	10.5	µg/L	
200123Q052	52	Gym Lobby - WF; Initial	1.00	<1.00	µg/L	
200123Q053	53	Gym Lobby - BF; Initial	1.00	<1.00	µg/L	



Date Collected:	22 Jan 2020
Date Received:	23 Jan 2020
Date Analyzed:	24 Jan 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200123Q054	54	Boy's Coach's Office Bathroom - SK; Initial	1.00	8.57	µg/L	
200123Q055	55	Girl's Sports Locker Room Bathroom - WF; Initial	1.00	6.45	µg/L	
200123Q056	56	Trainer's Vestibule - WF; Initial	1.00	16.8	µg/L	H
200123Q057	57	Trainer's Office - SK; Initial	1.00	6.48	µg/L	
200123Q058	58	Teacher's Faculty Lounge - SK; Initial	1.00	1.09	µg/L	
200123Q059	59	Hallway by Teacher's Faculty Lounge - WF; Initial	1.00	<1.00	µg/L	
200123Q060	60	Hallway by Room 219 - WF; Initial	1.00	<1.00	µg/L	
200123Q061	61	Hallway by Room 228 - WF; Initial	1.00	4.99	µg/L	
200123Q062	62	Hallway by Room 251 - WF; Initial	1.00	11.8	µg/L	
200123Q063	63	Hallway Ramp-2nd Floor - WF; Initial	1.00	<1.00	µg/L	
200123Q064	64	Hallway by Room 208 - WF; Initial	1.00	2.80	µg/L	
200123Q065	65	Hallway by Room 203 - SK; Initial	1.00	2.46	µg/L	
200123Q066	66	Hallway by Room 202 - WF; Initial	1.00	<1.00	µg/L	
200123Q067	67	Hallway by Room 202 - BF; Initial	1.00	<1.00	µg/L	
200123Q068	68	Room 216A - SK; Initial	1.00	14.9	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.



Laboratory Report

NYE Report #: 2200710-13952

February 14, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Huntington High School, Huntington, NY

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on February 14, 2020. New York Environmental analyzed the samples on February 14, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	12 Feb 2020
Date Received:	14 Feb 2020
Date Analyzed:	14 Feb 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
200214K007	1	Kitchen Prep @ A - SK; Initial	1.00	<1.00	µg/L	
200214K008	2	Kitchen Prep @ B - SK; Initial	1.00	<1.00	µg/L	
200214K009	3	Room 161 - SK; Initial	1.00	4.48	µg/L	
200214K010	4	Library Office (Room 110) - SK; Initial	1.00	1.39	µg/L	
200214K011	5	Trainer's Vestibule - WF; Initial	1.00	2.92	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation